

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

SF - 078385

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement Name and/or No.

8. Well Name and No.

Thompson LS 3S

9. API Well No.

30-045-33203

10. Field and Pool, or Exploratory Area

BASIN FRUITLAND COAL

11. County or Parish, State

SAN JUAN, NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well



Oil Well



Gas Well



Other

2. Name of Operator

BP AMERICA PRODUCTION COMPANY

3a. Address

PO BOX 3092 HOUSTON, TX 77253

3b. Phone No. (include area code)

281-366-4081

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1500' FNL & 800' FWL; SEC 34 30N 08W SWNW Mer NMP

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Acidize



Deepen



Production (Start/Resume)



Water shut-Off



Alter Casing



Fracture Treat



Reclamation



Well Integrity



Casing Repair



New Construction



Recomplete



Other **SPUD RPT**



Change Plans



Plug and Abandon



Water Disposal



Convert to Injection



Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or to recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

11/14/05 MIRU & SPUD 8 3/4" SURFACE HOLE & DRILL TO 210'. RU & LAND 7" 20 1/2" @ 201'. TIH & CMT lead w/57 sxs cls G; Density 14.80 ppg; Yield 1.330 cuft/sk. Circulated 1/2 bbl to surface. Pres tst Csg 250 low & 750 high psi. 30 Min; All tests OK. TIH & drill 6 1/4" hole 210' - 3150' TD 11/18/05. TIH & run 4 1/2" 10.5#; J-55 CSG to 3145'. TIH & CMT Lead w/270 sx; Density 11.70ppg; Yield 2.100 cuft/sx; Tail w/65 sxs; Density 13.50 ppg; Yield 2.260 cuft/sk. No Cement to surface. Top of Cement @ 1400'. CBL sent to BLM on 12/2/05

- No remediation required, but must monitor bradenhead pressure.

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title **Regulatory Analyst**

Signature

Cherry Hlava

Date **12/05/2005**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

DEC 14 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

**FARMINGTON FIELD OFFICE
BY *JB***

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD