Form 3160-5 (August 1999)

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

subject lease which would entitle the applicant to conduct operations thereon

Certify that the applicant holds legal or equitable title to those rights in the

2006 JAN 1 AM 11 21

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANGEMENT

RECEIVED 070 FARMINGTO

FORM APPROVED OMB No. 1004-0135

JAN 0 5 2006

FARMINGTON FIELD OFFICE

Date

114	Expire	s N	vember	30,	20
٠٠٠٠,		_			
1	ence Cerial No.	/			

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an IIII P. Abandoned well. Use Form 3160-3 (APD) for such proposals.

NM - 013688

. If Indian, Allottee or tribe Name

1. Type of Well Oil Well Gas Well Other	SU	BMIT IN TRI	PLICAT	TE – Other		ons on reverse	e side	If Unit or CA/Agree	ment	, Name and/or No.
30045-33200 3004	1. T	ype of Well	<u> </u>	<u> </u>	E) rain	Dis	:15 <i>[</i>		
BASIN DAKOTA & BLANCO MESAVERDE 4. Location of Well (Footage, Sec. T., R., M. or Survey Description) 11. County or Parish, State 1190' FNL & 885' FWL; SEC 25 T31N R10W NWNW Mer NMP 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Acidize Deepen Reclamation Production (Start/Resume) Water shut-Off Well Integrity Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Water Disposal SPUD & SET Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zon Attack the Bord under which the work will be performed or provide the Bond No. on file with BIM/BIA. Required subsequent reports shall be filed within 30 disllowing completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, a Form 31604 shall be filed only after all requirements, including reclamation, have been completed, and the operator is determined that the site is ready for final inspection. 169729/105 MIRU & Spfud.12 ½", Surface hole at 10:00 & Drill to 240". THH w/9:5/8"; 32#; H-40 ST&C CSG TO 237". Cement CSG LEAD w/75 sss; Yield 1.610 culfysx. No Cment to surface: Performed top job w/12 sas down the backside. 11/4/05 THI/AG CMT 233* D-III CMT to 194". TST BOPS 250/1050 psi; 150/150 psi; 30 Min. OK. DRILL CMT TO 230". 169729/105 MIRU & Spfud.12 ½", Surface hole at 10:00 & Drill to 240". THH w/9:5/8"; 32#; H-40 ST&C CSG @3669". THH & CMT TO CSG: SCA/VENGER w/25; 256; LEAD 365 sx, DENSITY Bid DPS 250/1050 psi; CSG/750 psi; 30 Min. OK. DRILL CMT TO 230". 169729/105 MIRU & Spfud.12 ½", Surface hole at 10:00 & Drill to 240"			CTION CO	OMPANY	<u></u>	**************************************	35 AGGGG	l .		
1100' FNL & 885' FWL; SEC 25 T31N R10W NWNW Mer NMP 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Notice of Intent			ON, TX 77		•	clude area code)				
TYPE OF SUBMISSION Acidize Deepen Alter Casing Fracture Treat Reclamation Reclamation Well Integrity Other Subsequent Report Change Plans Plug and Abandon Water Disposal Plug and Abandon Water Disposal SPUD & SET Final Abandonment Notice Convert to Injection Plug Back Convert Disposal Spring Adaptor to Available filed only after all requirements, including reclamation, have been completed, and the operator in determined that the site is ready for final inspection. (P) 19 10 10 10 10 10 10 10 10 10 10 10 10 10								•	State	
Acidize Deepen Production (Start/Resume) Water shut-Off Well Integrity Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Change Plans Plug and Abandon Water Disposal SPUD & SET Final Abandonment Notice Convert to Injection Plug Back Convert to Injection On file with Bulbla Required subsequent reports shall be filed within 30 dt following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed only after all requirements, including reclamation, have been completed, and the operator in determined that the site is ready for final inspection. (99/29/05 MIRU & Spud 13 ½ Surface hole at 10:00 & Drill to 240'. TIH w/ 9:5/8"; 32#; H-40 ST&C CSG TO 237'. Cement CSG LEAD w/ (75 six; Yield 1.610 cuft/ss. No Cment to surface; Performed top job w/12 six down the backside. 11/4/05 TIH; TAG CMT @34'. Drill CMT to 194'. TST BOPS 250/1500 psi; CSG 750 psi 30 MIN. OK. DRILL CMT TO 230'. Priss test CSG to 750 PSI 30 Min. All Test OK. DRILL 8''. "240' - 3679'. TIH & LAND' 7"; 20# J-55 ST&C CSG @3669'. TIH & CMT CSG. SCAVENGER w/25 §ixs; LEAD 365 sx. DENSITY @11.7 PPG YIELD 2.610 CMT; TAIL w/65 sx. 31.5 PPG YIELD 1.260 POZ. CIRCULATED 51 bbls GOOD CEMENT TO SURFACE. PRES TST CSG TO 1500 PSI FOR 30 MIN OK. DRILL OUT CMT & RAT HOLE FROM 3619' - 3679' / TIH & DRILL 6'%2'-HOLE 3679' - 7988' TMD & 7788' TVD on 11/12/05. TIH w/4 ½" 13.64, P/110 LT&C CSG & LAND @7097'. TIH & CEMENT 4 ½" CSG; CMT LEAD w/150 sxs; 9.50 ppg LITECRETE YIEL 2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT.		12.	CHECK A	PPROPRIATE	BOX(ES) TO	O INDICATE NATU	JRE OR NO	OTICE, REPORT, OR OTH	IER I	DATA
Alter Casing	TYPE OF SUBMISSION TYPE OF ACTIO							FACTION		
Alter Casing Fracture Treat Recolamation Well Integrity Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Plug Back Convert to Injection Plug Back Convert to Injection Plug Back Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zon Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BlA. Required subsequent reports shall be filed within 30 dt following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed only after all requirements, including reclamation, have been completed, and the operator he determined that the site is ready for final inspection. (169/28/95 MIRU & Spud.13 ½: Surface hole at 10:00 & Drill to 240'. TIH w/ 9:5/8"; 32#; H-40 ST&C CSG TO 237'. Cement CSG LEAD w/ 75 sxs; Yield 1.610 cuft/sx. No Cment to surface; Performed top job w/12 sxs down the backside. 11/4/05 TIH; TAG CMT @34'. Drill CMT to 194'. TST BOPS 250/1500 psi; CSG.750 psi 30 MIN. OK. DRILL CMT TO 230'. Press test CSG to 750 Psi 30 Min. All Test OK. DRILL 8 ½" 240' - 3679'. TIH & LAND 7"; 20# J-55 ST&C CSG @3669'. TIH & CMT CSG: SCAVENGER w/25 sks; LEAD-365 sx, DENSITY @11.7 PPG YIELD 2.610 CMT; TAIL w/65 sx. 13.5 PPG YIELD 1.260 POZ. CIRCULATED 51 bbls GOOD CEMENT TO SURFACE. PRES TST CSG TO 1500 PSi FOR 30 MIN OK. DRILL OUT CMT & RAT HOLE FROM 3619' - 3679'. TIH & CEMENT 4 ½" CSG: CMT LEAD w/150 sxs; 9.50 ppg LITECRETE YIEL 2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT.	a			Acidize		Deepen	Q ,	Production (Start/Resume)		Water shut-Off
Subsequent Report Change Plans Plug and Abandon Water Disposal SPUD & SET Plug Set Final Abandonment Notice Convert to Injection Plug Back Plug Back Convert to Injection Plug Back Plug Back Convert to Injection Plug Back Plug Back Plug Back Convert to Injection Plug Back Required subsequent reports shall be filed within 30 de following completion or recompletion in a new interval, a Form 31604 shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the involved shall be filed within 30 de following completion or the i	Ш	Notice of Intent		Alter Casing		Fracture Treat	Q ,	Reclamation		Well Integrity
Canage Plans Plug and Abandon Water Disposal Strub & S	_			Casing Repa	ir 📮	New Construction	, 🗀 1	Recomplete		Other
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zon Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 di following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator hetermined that the site is ready for final inspection. (99/29/05 MIRU & Spud_13 ½) Surface hole at 10:00 & Drill to 240'. TH w/9/5/8"; 32#; H-40 ST&C CSG TO 237'. Cement CSG LEAD w/7/5 sxs; Yield 1.610 cuft/sx. No Cment to surface; Performed top job w/12 sxs down the backside. 11/4/05 TH; TAG CMT @34'. Drill CMT to 194'. TST BOPS 250/1500 psi; CSG 750 psi 30 MIN. OK. DRILL CMT TO 230'. Press test CSG to 750 PSI 30 Min. All Test OK. DRILL 8 ½" 240' - 3679'. TH & LAND 7", 20# J-55 ST&C CSG @3669'. TH & CMT CSG; SCAVENGER w/25 xxs; LEAD 365 xx. DENSITY @11.7 PPG YIELD 2.610 CMT; TAIL w/65 xx. 3.3.5 PPG YIELD 1.260 POZ. CIRCULATED 51 bbls GOOD CEMENT TO SURFACE. PRES TST CSG TO 1500 PSI FOR 30 MIN OK. DRILL OUT CMT & RAT HOLIFROM 3619' - 3679'. TH & DRILL 6 ½"-HOLE 3679' 7988' TMD & 7788' TVD on 11/12/05. THH w/4 ½" 13.6#, P-110 LT&C CSG & LAND @7097'. TH & CEMENT 4 ½" CSG; CMT LEAD w/150 sxs; 9.50 ppg LITECRETE YIEL 2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT.		Subsequent Report		Change Plan	ıs 📮	Plug and Abando	. 🗅	Water Disposal		SPUD & SET
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zon Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 de following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed on testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator in determined that the site is ready for final inspection. (09/29/05 MIRU & Spud_13 ½", Surface hole at 10:00 & Drill to 240'. TH w/ 9.5/8"; 32#; H-40 ST&C CSG TO 237'. Cement CSG LEAD w/ (7.5 sxs; Yield 1.610 cuft/sx. No Cment to surface; Performed top job w/12 sxs down the backside. 11/4/05 TIH; TAG CMT @34'. Drill CMT to 194'. TST BOPS 250/1500 psi; CSG.750 psi 30 MIN. OK. DRILL CMT TO 230'. Press test CSG to 750 PSI 30 Min. All Test OK. DRILL § ½" 240' - 3679'. TIH & LAND 7", 20# J-55 ST&C CSG @3669'. TIH & CMT CSG; SCAVENGER w/25 \$\frac{23}{25}\frac{23}{25}\frac{25}{25}		Final Abandonment No	otice 🖵	Convert to I	njection 🖵	Plug Back				
(75 sxs; Yield 1.610 cuft/sx. No Cment to surface; Performed top job w/12 sxs down the backside. 11/4/05 TIH; TAG CMT @34'. Drill CMT to 194'. TST BOPS 250/1500 psi; CSG 750 psi 30 MIN. OK. DRILL CMT TO 230'. Press test CSG to 750 PSI 30 Min. All Test OK. DRILL 8 ½" 240' - 3679'. TIH & LAND 7", 20# J-55 ST&C CSG @3669'. TIH & CMT CSG; SCAVENGER w/25 sxs; LEAD 365 sx. DENSITY @11.7 PPG YIELD 2.610 CMT; TAIL w/65 sx.13.5 PPG YIELD 1.260 POZ. CIRCULATED 51 bbls GOOD CEMENT TO SURFACE. PRES TST CSG TO 1500 PSI FOR 30 MIN OK. DRILL OUT CMT & RAT HOLIFROM 3619' - 3679' / TIH & DRILL 6 ½" HOLE 3679' - 7988' TMD & 7788' TVD on 11/12/05. TIH w/4 ½" 1.1.6#, P-110 LT&C CSG & LAND @7097'. TIH & CEMENT 4 ½" CSG; CMT LEAD w/150 sxs; 9.50 ppg LITECRETE YIEL 2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT.	If the Att follows	the proposal is to deepe tach the Bond under willowing completion of the tring has been complete	n directional tich the wor te involved td. Final A	lly or recomple rk will be perfo operations. If the bandonment No.	te horizontally ormed or provi the operation r otices shall be	, give subsurface loca de the Bond No. on a esults in a multiple of	itions and m file with BL completion or	easured and true vertical dep M/BIA. Required subsequer recompletion in a new inter	oths o nt rep rval, a	f all pertinent markers and zones. orts shall be filed within 30 days a Form 3160-4 shall be filed once
CIRCULATED 51 bbls GOOD CEMENT TO SURFACE. PRES TST CSG TO 1500 PSI FOR 30 MIN OK. DRILL OUT CMT & RAT HOLIFROM 3619' – 3679', TIH & DRILL 6'1/2" HOLE 3679' – 7988' TMD & 7788' TVD on 11/12/05. TIH w'4 '/" 1,1.6#, P-110 LT&C CSG & LAND @7097'. TIH & CEMENT 4 '/" CSG; CMT LEAD w/150 sxs; 9.50 ppg LITECRETE YIEL 2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT.	(75 sx 11/4/ (Press CSG;	s; Yield 1.610 cuft/s 05 TIH;TAG CMT test CSG to 750 PS SCAVENGER w/2	x. No Cm @34'. Dri I 30 Min. 5 sxs; LE	nent to surface II CMT to 19 All Test Ok AD-365 sx . D	e; Performe 14'. TST BC (. DRILL § DENSITY @	d top job w/12 sx DPS 250/1500 psi; '%'' 240' - 3679'. 11.7 PPG YIELD	s down th CSG 750 TIH & L. 2.610 CM	e backside. psi 30 MIN. OK. DRILI AND 7", 20# J-55 ST&C T; TAIL w/65 sx.13.5 P	L CM C CS PPG '	4T TO 230' G @3669'. TIH & CMT 7'' YIELD 1.260 POZ .
2.520. TAIL w/202 SX CLS G POZ, DENSITY 13.PPG; YIELD 1.440. RIG REL 11/13/05 @12:00 hrs. TOP OF CEMENT WILL BE NOTED ON COMPLETION REPORT. 14. I hereby certify that the foregoing is true an dcorrect Name (Printed/typed)	CIRC FROI	CULATED 5 <u>1 b</u> bls C M 3619' – 3679' / T	OOD CE	MENT TO S LL 6 ¼º HO	URFACE. [4 LE 3679" –	PRES TST CSG T 7988' TMD & 77	O 1500 PS 88' TVD	SI FOR 30 MIN OK. DF on 11/1 2/05	RILL	OUT CMT & RAT HOLE
14. I hereby certify that the foregoing is true an dcorrect Name (Printed/typed)										771411
Name (Printed/typed)	тор	OF CEMENT WI	LL BE NO	OTED ON C	OMPLETI	ON REPORT.			J. S.	17 15 19 15 16 77 m
Cherry Hlava Title Regulatory Analyst			oregoing is	true an dcorre	ct			1	188	ON TON TO SE
	_	herry Hlava				LTOL	Dogula	tory Analyst	2	ON UNIVERSE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter witin its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Office