

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-031-20737	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name SANTA FE PACIFIC RAILROAD	
8. Well No. 56	
9. Pool name or Wildcat Miguel Creek Gallup	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: _____	
2. Name of Operator ROBERT L. BAYLESS	
3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499	
4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet from the <u>SOUTH</u> Line and <u>660</u> Feet from The <u>WEST</u> Line Section <u>21</u> Township <u>16N</u> Range <u>6W</u> NMPM <u>McKINLEY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6437' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Robert L. Bayless plugged and abandon this well September 18, 2002. The procedure is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom McCarthy TITLE ENGINEER DATE 11/7/02

TYPE OR PRINT NAME Tom McCarthy TELEPHONE NO. (505) 327-2659

(This space for State Use) H. Villanueva DEPUTY OIL & GAS INSPECTOR, U.S.I. DATE DEC 20 2005

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: 12-20-05

Robert L. Bayless

Plug and Abandon Report

SFPRR No. 56

1980' FSL & 660' FWL, Section 21, T16N, R6W

McKinley County, NM

9/18/2002: Rig up JC Well Service. Pressure test tubing with rods and pump in hole. Tested OK. Trip out rods and pump, and used rod count as tally. Tag PBD at 822'. Roll hole with water. Mix and spot 24 sack bottom plug at 822'. Trip out tubing and WOC. Trip in and tag plug at 570'. Pressure test of casing was good. Perforated squeeze holes at 100'. Mix and pump 57 sacks cement. Circulated cement to surface. Rigged down. Class B cement was used.

Installed abandonment marker and backfilled pit. Cleaned up location.