## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DIGITAL CIT. I					Rev	iseu 1-1-09	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION 2040 Pacheco St.			WELL API NO.			·	
			30-043-20999				
P.O. Drawer DD, Artesia, NM 88210  Santa Fe, NM 87505			5. Indicate Type of	of Lease STATE X	FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Ga	s Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PORPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or	Unit Agreement N	ame	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					THE BOOK		
(FORM C-101) FOR SUCH PROPOSALS)				STATE 21-6-36		A 18	) <u>)</u>
1. Type of Well:				STATE 21-0-30		B 2006	183
OIL GAS WELL X	OTHER					TEIVED	
2. Name of Operator				8. Well No.	is and	on <b>s</b> . Div.	72
SG INTERESATS I LTD, c/o NIKA ENERGY OPERATING, LLC					#39 19	NETT 8	224
3. Address of Operator				9. Pool name or V	(2) <b>al</b> (1)	.6	7.3 2.7
PO BOX 2677, DURANGO, CO	970) 25	59-2701		FRUITLAND CO	OAL (71629)	CUR C2 30.32	<u>Y</u>
4. Well Location	660 Part France Tha	Cauth	T : d	724	Foot From The	West	r :
Unit Letter M : 6	Feet From The	South	Line and	124	Feet From The	West	Line
Section 36	Гownship 21N Rai	nge 6W		NMPM		Sandova	l County
10. Elevation (Show whether DF, RKB, RT, GI				R, etc.)			
6886' GR							
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
11. NOTICE OF INTENTION TO:				SUBSEQUEN	NT REPORT	OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORI	k [	ALTERING CAS	SING	
TEMPORARILY ABANDON			COMMENCE DRII	LLING OPNS.	PLUG AND ABA	ANDONMENT	
PULL OR ALTER CASING CASING TEST A			ND CEMENT JOB	]			
OTHER:			OTHER: Drilling	g & Completion Up	odate	<del></del>	X
12. Describe Proposed or Completed Operation	ns (Clearly state all pertinent details,	and give per	rtinent date, including est	imated date of starting any	proposed		
work) SEE RULE 1103.							
(11/10/05) Spud & drill 12-1/4" hole to 175' KB. Circ & cond hole. RIH w/4 jts 7" 20# J-55 ST&C csg; set @ 164' KB w/170							
sx Class 'B' w/2% CaCl, 1/4#/sk Flocele. Circ 10 bbls to surface. Drill cem & shoe. Continue drilling with 6-1/4" hole to TD							
950'. Logged well. RIH w/23 jts 4-1/2" 10.5# J-55 ST&C csg; set @ 933.01' KB w/165 sx Class 'B', 1/4#/sk Flocele, 5#/sk							
Gilsonite. Circ 14 bbls to surface. WOC							
.,							
(11/17/05) MIRUSU RIH w/	3-7/8" bit, scraper on 2-	3/8" tbg	;; CO to PBTD (	890'). Circ hole	clean w/2% KC	i wtr. Press	test
csg to 3000 psi, ok. Rn GR/C		_					
773'-777' (4'); 780'-784' (4'); total 9', 36 holes. PU SPIT tool; straddle ea set perfs. BD & acidize w/total 500 gal 15% DI FE							
acid; overflush w/10 B/KCl w			-			_	
(Continued on Page 2 attache	d)			•		, ,	
I hereby certify that the information a	bove is true and complete to the	best of my	knowledge and belief				
SIGNATURE Marce	a slewart	-		ent for SG Interests	DATE	01/06/0	)6
TYPE OR PRINT NAME Mai	rcia Stewart				TELEPHONE NO.	(970) 259-	2701
(This space for State Use)	ı			CAC PARTICIPANT	ease as f		22-
APPROVED BY A. VILLA	nueva		TITLE	IN THE PERSON FRANCES	DATE	EB 142	<u> 2006</u>
CONDITIONS OF APPROVAL, IF ANY							

SUNDRY NOTICE – FORM 3160-3 dated January 5, 2006

Page 2

SG INTERESTS I, LTD STATE 21-6-36 #3 (SWSW) M-SEC 36-T21N-R6W SANDOVAL COUNTY, NM

Prem 20/40 Brady Sand, 422 gal flush. Clean out hole to PBTD w/2% KCl wtr. Swab well. Land 26 jts 2-3/8" 4.7# J-55 tbg w/NC @ 843'; SN on top of btm jt @ 807'. RIH w/insert pump, 2 ea 1-1/2" sinker bars, 30 ea.  $\frac{3}{4}$ " rods; land, seat w/polish rod. Ck pump action to 600 psi, ok.

Set pump jack; well on test; WOPL