Submit 3 Copies To Appropriate Distric	ct	State of N	New Me	xico		Form C-103
Office District I		Energy, Minerals a	and Natu	ral Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 88240					WELL API NO.	en e
District II	OIL CONCEDUATION DIVISION					0-045-10770
1301 W. Grand Ave., Artesia, NM 882	10				5. Indicate Type	of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	n	1220 South			SPATE	FEE
District IV	Santa Fe. INVI 8/3U3					as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	ncis Dr., Santa Fe, NM				B-11017-28-NM	
87505			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	A Office of the second		
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PRO	OPOS/	ALS TO DRILL OR TO DEEP	EN OR PLI	A CONTROL A	Brookhaven Con	n G
DIFFERENT RESERVOIR. USE "AP PROPOSALS.)	PLICA	ATION FOR PERMIT (FORM		ECENED P.	<u> </u>	
1. Type of Well:					8. Well Number	
Oil Well Gas Well	xΓ	Other		CONS. DIN. CONS. DIN. CONS. DIN. S	<b>)</b> #9	
2. Name of Operator		Oulei			9. OGRID Numl	her
•	<sup>7</sup> 00 (	Company I D	4.915	, no. 6 m	14538	SCI .
Burlington Resources Oil & C	Jas C	ompany Lr		abl SI 71 \\	10. Pool name of	- Wildoot
3. Address of Operator	Th. # 0	# 400 4200		CIALIAN A		
P.O. Box 4289, Farmington, N	NIVI 8	7499-4289			Blanco MV / Bas	3III DK
4. Well Location						
Unit Letter H :_		<u>1450</u> feet from the	North	line and 1	190 feet from the	<u>East</u> line
Section 16		Township 3			NMPM San Juan	n County
	College College	11. Elevation (Show wh	ether DR,	RKB, RT, GR, etc.,		
	1					A Section 1
12 Cha	-1- A	mmamuiata Daw ta Ind	dianta NI	otume of Motion	D am amt am Other	n Data
		ppropriate Box to Inc	ncate in			
		TENTION TO:			SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WOR	к 🗆	ALTERING CASING 🔲
	_					<u></u>
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND
DULL OF ALTER CASING	_	A	_		57	ABANDONMENT
PULL OR ALTER CASING		MULTIPLE		CASING TEST AN	ND 🖾	
		COMPLETION		CEMENT JOB		
OTHER:				OTHER: Recoi	mpletion (includes	squaaza datail)
OTTEN.			لــا	X	inpletion (includes	squeeze detail)
13. Describe proposed or co		eted operations (Clearly	ctate all t		d give pertinent de	tes including estimated date
of starting any proposed	Jinpi d wor	V) SEE DITTE 1102 E	state an p or Multipl	le Completions: At	i give periment da toch wellbore dieg	ram of proposed completion
	ı woı	k). SEE KULE 1103. F	or wruitip	ie Completions. At	tacii welibole diagi	ram of proposed completion
or recompletion.						
1/17/0/ NIDII A 440 ND I	37TT 1	WILDOOD TOOK - W	TOTAL /	21.0 . 21.1.0	4610 / 45501 / 11	
1/17/06 MIRU Aztec 449. ND V						
TOOH w/mill. TIH w/5-1/2" Pkr & set @ 4750'. Tried to test. Moved pkr to 5112' - no test. Moved to 5500', pkr kept hanging up @						
5300'. TOOH w/packer. POOH w/pkr. TIH w/mill & milled from 5300' to 5362' (milled 3 days). Fell out of bad spot in casing.						
TOOH w/mill. TIH w/packer & set @ 6945'. PT pkr - No test. TOOH w/pkr. TIH w/5-1/2" RBP & 5-1/2" pkr to 6920'. Set 5-1/2"						
RBP @ 6920'. Set pkr & isolated leak @ 5389' - 5450'. 1/31/06 Called OCD - Henry V. gave us verbal approval to squeeze w/150						
sx cement.						
I hereby certify that the informat	ion a	bove is true and complete	e to the be	est of my knowledge	e and belief. I furth	ner certify that any pit or below-
grade tank has been/will be constructe	d or c	losed according to NMOCD g	guidelines [	], a general permit 📋	or an (attached) alter	native OCD-approved plan .
		00 01				
SIGNATURE / Telse	10	Cle T	ITLE <u>Sr</u>	. Regulatory Specia	ılist DATE _	1/23/06
1	r	0				
Type or print name Pats:	y Clu	gston E-mail add	ress: pcl	ugston@br-inc.com	Telephone No.	. 505-326-9518
			-			
(This space for State use)						
(2 mb space for state use)						
	<del></del> -	<del></del>		**		
. / /	A					FEB 2 7 2006
ADDDD OVED BY H. I	10 a			uty or a gas insi	PECTOR, DIST. (3)	
APPPROVED BY 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	u v	mueva I	TTLE			DATE
Conditions of approval, if any:						

Brookhaven Com G #9 API – 30-045-10770 Recompletion & squeeze detail Page 2

2/2/06 RU WH & ran GR/CCL. Perf'd Pt Lookout @ 4808', 10', 12', 14', 58', 61', 64', 4924', 26', 28', 45', 47', 58', 59', 63', 69', 90', 92', 5007', 10', 13', 30', 33', 36', 42', 45', 48', 55', 61', 68', 71', 90', 98'. = 33 holes. RU to frac. Pumped 10 bbls 15% HCL. Pumped 12,500 gal foam pad @ 60% Slickfoam w/125,000# 20/40 Brady sand. Displaced w/10 bbls fluid & 12,000 scf N2. Total fluid to recover 1178 bbls, total N2 1,380,000 scf N2. RD frac. Flowed back 3 days.

POOH w/packer. TIH w/4-5/8" bit & tagged up @ 5109'. Bottom perf @ 5098'. TOC @ 5142'. C/O to TOC. Blew well w/air & mist C/O. TOOH w/bit. TIH & latched on RBP W 6920'. POOH. TIH w/bit & C/O to CIBP @ 7150'. Milled out CIBP. Flowed well back naturally & w/air mist C/O to PBTD - 2 days. POOH w/mill. RIH w/225 jts 2-1/16" tbg and landed @ 7293'. ND Bop, NU WH. Pumped off expendable check. RD & released rig 2/15/06.