Form 3160-5 (August 2007)

1. Type of Well

3a. Address

RECEIVED UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

SF-078945

Farmin SUNDRY NOTICES AND REPORTS ON WELLS Burdo not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. San Juan 29-7 Unit 8. Well Name and No. **SAN JUAN 29-7 UNIT 544** 9. API Well No.

6. If Indian, Allottee or Tribe Name

Oil Well X Gas Well Other 2. Name of Operator **Burlington Resources Oil & Gas Company LP** 30-039-25007 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 **BASIN FRUITLAND COAL** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State ULB (NWNE), 790' FNL & 1365' FEL, SEC. 4, T29N, R7W Rio Arriba **New Mexico**

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION

Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
X Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
	Casing Repair	New Construction	Recomplete	X Other	
	Change Plans	Plug and Abandon	Temporarily Abandon	INSTALL JET	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	PUMP	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof					

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/25/15 MIRU AWS 993. Pulled rods & pump. ND WH, NU BOP. PT-OK. POOH w/2-3/8" tubing. Circ hole clean. Used air, mist, foamer and corrosion inhibitor. RIH w/7 jts 2-7/8", 6.5# J-55 tubing & jet pump body, 82 jts of 3-1/2", 9.3# J-55 tubing and landed @ 2982'. 9/30/15 RIH w/inner string of tubing - 1 1-1/4" jet pump nozzle, 9 jts 1-1/4" tubing, and 80 jts 2-1/16" tubing set @ 2966'. Check jet pump action - OK. ND BOP, NU WH. Set wrap around slips on tubing string, NU pack off. RD & released rig @ 1700 hrs. 9/30/15.

OIL CONS. DIV DIST. 3

ACCEPTED FOR RECORD

OCT 06 2015

OCT 0 2 2015

FARMINGTON FIELD OFFICE

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Patsy Clugston** Staff Regulatory Technician Title 10/2/2015 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction