

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

**Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

5. Lease Serial No.

NM0560223

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or N

8. Well Name and No.

Frew Federal 6

9. API Well No.

30-045-22650

10. Field and Pool, or Exploratory Area

Waw Fruitland Sand PC

11. County or Parish, State

San Juan, New Mexico

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Running Horse Production Company

3a. Address

PO Box 737, Ignacio, CO 81137

3b. Phone No. (include area code)

970-563-0145

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1850' FNL & 1850' FWL, Section 19, T26N-R12W

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed. Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator determined that the site is ready for final inspection.)

Running Horse Production Company proposes to plug and abandon this well according to the attached prognosis.

RECEIVED

2003 JUN 19 PM 5:07

070 Farmington, NM



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Robert J. Voorhees

Signature

*Robert J. Voorhees*

Title

Vice President Engineering & Development

Date

June 5, 2003

**THIS SPACE FOR FEDERAL OR STATE USE**

Approved by

Original Signed: Stephen Mason

Title

Date

JUN 27 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

June 5, 2003

Running Horse Production Company

P&A Procedures for Frew Federal #6

Location: NW/4 Sec 19, T26N-R12W, San Juan County, NM

Field: Waw Fruitland Sand PC

Surface: Navajo

Lease: NM 0560223

Elevation: 6088'

Production String: 2 7/8" @1329'

PBTD: 1297'

Procedure:

1. MIRU service unit.
2. NU 2 3/8" relief line. Blow well down and kill with water if necessary.  
Laydown tubing.
3. Connect cement truck directly to 2 7/8" tubing and fill casing with 40 sx (47 cu ft) of Class H cement with 1/4#/sk celloflake. Pump cement until tubing stands full.
4. Cut off wellhead and install dry hole marker. Reclaim location as per BLM specifications.