



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

July 2, 2003

Jim Hicks
Chaparral Energy LLC
701 Cedar lake Blvd
Oklahoma City, OK 73114

RE: Navajo Tribe BU#2, B 34-26N-18W API 30-045-21812

Dear Mr. Hicks:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before September 15, 2003.

Reference RBDMS CTP0317563068 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: BLM Farmington
CTP
Well File