Form 31:60-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 1 6 2013

FORM APPROVED OMB No. 1004-0137

	l .							
		Eiol	40	Offi	Expires:	July	31,	20
-armi		1-101	Cit	2111	00			

Fairin	5. Lease Serial No.	ant
Bureau C	5 Lease Serial No. of Land Manageme	NMSF-07841

		DU	lleau q	NMSF-078410			
Do not use	DRY NOTICES AND REPO this form for proposals t well. Use Form 3160-3 (A	n	6. If Indian, Allottee or Tribe N	íame			
	BMIT IN TRIPLICATE - Other insi	7. If Unit of CA/Agreement, Na	ame and/or No.				
1. Type of Well Oil Well	Gas Well Other			8. Well Name and No. San Jua	an 29-5 Unit 4C		
2. Name of Operator			9. API Well No.	20.00054			
	iny		30-039-29351				
3a. Address		3b. Phone No. (include area co	de)	10. Field and Pool or Explorate	ory Area		
382 Road 3100, Aztec, N	505-599-3400		Gobenador PC/Blanco Mesaver				
4. Location of Well (Footage, Sec., T.,R Surface Unit F (S	WL, Sec. 6, T29N, R05	W	11. Country or Parish, State Rio Arriba	, New Mexico			
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NO	TICE, REPORT OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	R	teclamation	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	X R	Recomplete	Other		
<u> </u>	Change Plans	Plug and Abandon	T	emporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	77	Vater Disposal			

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

See Attached.

ACCEPTED FOR RECORD

JUL 23 203

that the applicant holds legal or equitable title to those rights in the subject lease which would

ARMINGTON FIETD OFFICE

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Etta Trujillo

Title

Operations/Regulatory Technician - Sr.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Operations/Regulatory Technician - Sr.

Title

Date

Title

Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

entitle the applicant to conduct operations thereon.

6/14/2018 - MIRU. ND WH. NU BOP & . SIW. SDFN.

6/15/2018 – Load 4.5" X 7" annulus w/43bbls pkr fluid. TOOH w/2-3/8" tbg. TIH w/3-3/4" bit & 4.5" csg scraper to 4010' w/no issues, TOH. TIH & set 4.5" CIBP @ 3830'. Load hole w/55bbls fw treated w/biocide. Circ 80bbls. PT 4.5" CIBP & csg to 2025# 20min no leaks. Good test. TOH LD 123jts. ND BOPE, NUT & SIW. SDFW.

6/18/2018 – NDT, NU frac stack. PT frac stack, 4.5" csg & CIBP @ 4000# 30min w/no leak-off. Good test. RU WL. Perf'd Pictured Cliffs, 82 holes @ 2 SPF, f/3623' – t/3664' 2 runs, 44" dia, 60 deg phasing. RD WL. SIW. SDFN.

6/29/2018 – MIRU frac crew. Prime test. Foam frac'd Pictured Cliffs w/150,040# 20/40 sand & 29,512gal 20# linear gel & 1.09 million SCF N2. 70Q. RD.

7/7/2018 - MIRU. Open well to FB tank. Continue to flow well overnight.

7/8/2018 – RU WL. RIH & set 4.5" CBP (kill plug) @ 3550'. TOOH. RD WL. Load 4.5" csg w/57bbls. PT kill plug 1000# 10 min w/no leak-off. ND frac tree, NU BOPE, PT. PU 2-3/8" tbg & TIH w/3-7/8" junk mill. Mill out kill plug @ 3550' w/air & mist. CO to CIBP @ 3830'. Circ hole clean. PU to 3556'. SIW. SDFN.

7/9/2108 – Mill out CIBP @ 3830' w/air & mist. TIH w/junk mill, CO 12' of fill to PBTD @ 6178'. TOH w/mill. TIH & land 187jts 2-3/8" 4.7# J-55 @ 5823', SN @ 5821'. Test tbg to 580# 10min no leak-off. Good test. Pump off check. ND BOP. NU WH. RD. Rig released.

Well is now producing as Pictured Cliffs/MesaVerde commingle under DHC 4050AZ