Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

NMSF080505-A

SUNDRY NOTICES AND REPORTS	6. If Indian, Allottee or Tribe	6. If Indian, Allottee or Tribe Name				
Do not use this form for proposals to dri abandoned well. Use Form 3160-3 (APD) :						
SUBMIT IN TRIPLICATE - Other instruction		7. If Unit of CA/Agreement, N	Jame and/or No			
1. Type of Well	ns on page 2.		Juan 28-6 Unit			
Oil Well X Gas Well Other		8. Well Name and No.				
			n 28-6 Unit 211E			
2. Name of Operator Hilcorp Energy Company		9. API Well No. 30-039-30071				
	hone No. (include area code)	10. Field and Pool or Explorat				
382 Road 3100, Aztec, NM 87410	505-599-3400		averde/Basin Dakota			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		11. Country or Parish, State				
Surface Unit L (NWSW) 1555'FSL & 830'FWL, Se	ec. 09, T28N, R06W	Rio Arriba	, New Mexico			
12. CHECK THE APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF N	OTICE, REPORT OR OTH	ER DATA			
TYPE OF SUBMISSION	TYPE OF A	CTION				
X Notice of Intent Acidize	Deepen	Production (Start/Resume)	Water Shut-Off			
Alter Casing F	racture Treat	Reclamation	Well Integrity			
Subsequent Report Casing Repair	New Construction X	Recomplete	Other			
Change Plans P	Plug and Abandon	Temporarily Abandon				
Final Abandonment Notice Convert to Injection P 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, inc	Plug Back	Water Disposal				
Hilcorp Energy Company plans to recomplete the sub- existing Dakota with the Mesaverde. Attached is the Mapplication will be submitted and approved before the reclamation will be performed after surface disturbing **Please note: MV is pending approval of well density	IV C102, recomplete pework proceeds. A closs activities. hearing* BLM'S APPRO	procedure & wellbore so osed loop system will b	chematic. The DHC e utilized. Interim F THIS SEE AND			
HOLD G104 FOR Density exprograms	ACTION DOE OPERATOR F	BLM'S APPROVAL OR ACCEPTANCE OF BLM'S APPROVAL OR ACCEPTANCE OF BLM'S APPROVAL OR ACCEPTANCE OF BLM'S ACCE				
NOV 15 2013	0.112	LAND INDEX	Notify NMOCD 24 hrs prior to beginning			
	0.112	LANDINDEN	Notify NMOCD 24 hrs prior to beginning			
DISTRICT 11 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	02	LANDINDEN	Notify NMOCD 24 hrs prior to beginning			
DISTRICT III		Regulatory Technician -	Notify NMOCD 24 hrs prior to beginning operations			
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		LANDINDE	Notify NMOCD 24 hrs prior to beginning operations Sr.			
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Signature	Title Operations	Regulatory Technician -	Notify NMOCD 24 hrs prior to beginning operations Sr.			

entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 248673



NOV 15 2018



WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-30071	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 211E
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6806


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
L	9	28N	06W		1555	S	830	W	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 283.40 S/2 284.20		13. Joint or Infill		14. Consolidation Code			15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech Sr

Date: 11/06/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

John A Vukonich

Date of Survey:

5/25/2006

Certificate Number:

14831



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 211E MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-3/8" tubing set at 8,021'.
- 3. Set a 4-1/2" plug at +/- 6,350' to isolate the Dakota. (Note: TOC at 3,350' by CBL)
- 4. Load the hole and pressure test the casing.
- 5. N/D BOP, N/U frac stack and pressure test frac stack.
- 6. Perforate and frac the Mesa Verde formation (Top Perforation @ 5,150'; Bottom Perforation @ 6,050').
- 7. Isolate frac stages with a plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 8,136'. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 211E MESA VERDE RECOMPLETION SUNDRY

NOV 1 5 2018

