Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary **Gabriel Wade**, Acting Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 1/28/19 Well information:

Hilcorp, Fogelson Gas Com #1E, API# 30-045-30274

Application Type:

P&A Drilling/Casing Change Location Change

Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)

Other:

Conditions of Approval:

- Notify the OCD 24hrs prior to beginning operations.
- The initial CIBP must be placed no higher than 50' above the existing perforations.
- A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
 - 24hr notice is required to be provided to the agencies prior to performing the MIT.
- After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures.

NMOCD Approved by Signature

<u>2/21/19</u> Date

1					DEN/	ED					
		RECEIVED									
)		UNITED STAT	JAN	29	2019						
	Form 3160-5 (August 2007)	DEPARTMENT OF THE				FORM APPROVED OMB No. 1004-0137					
	(Tugust 2007)	BUREAU OF LAND MAI					ly 31, 2010				
				Farming Bureau of L	ton Fie and N	5. Lease Serial No.	079289A				
	SU	NDRY NOTICES AND REPO	ORTS O			6. If Indian, Allottee or Tribe Nat					
	Do not u	se this form for proposals	to drill o	r to re-enter a	n						
	abandone	d well. Use Form 3160-3 (A	PD) for	such proposa	ls.						
		SUBMIT IN TRIPLICATE - Other ins	tructions o	n page 2.		7. If Unit of CA/Agreement, Nan	ne and/or No.				
	1. Type of Well										
	Oil Well	X Gas Well Other				8. Well Name and No. Fogelson Gas Com 1E					
	2. Name of Operator					9. API Well No.					
		Hilcorp Energy Compa	any			30-045-30274 10. Field and Pool or Exploratory Area					
	3a. Address		3b. Phone	No. (include area co	/						
	382 ROAD 3100, AZTE	C NM 87410		505-599-3400		Basin Dakota /	Blanco Mesaverde				
	4. Location of Well (Footage, Sec., T.				1	11. Country or Parish, State					
	Surface Unit N (S	ESW), 955' FSL & 1515' FV	VL, Sec.	26, T30N, R11	7 VV	San Juan ,	New Mexico				
	12. CHECK	THE APPROPRIATE BOX(ES)	TO INDI	CATE NATURE	OF NC	TICE, REPORT OR OTHE	R DATA				
	TYPE OF SUBMISSION			TYPE	OF AC	CTION					
	X Notice of Intent	Acidize	Deepe	'n		Production (Start/Resume) Water Shut-Off					
		Alter Casing	·	re Treat		Reclamation	Well Integrity				
	Subsequent Report	Casing Repair		Construction		Recomplete	Other				
		Change Plans		and Abandon		Temporarily Abandon					
0	Final Abandonment Notice	Convert to Injection	Plug I			Water Disposal					
E	hanna	Dperation: Clearly state all pertinent deta					e duration thereof.				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)											
	existing Dakota with t	erde formation and dow A DHC application will erim reclamation will be	be filed and								
		a second		BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS							
		NMOCD									
		FEB 1 2 2019									
						AND MOMINTANDS					
		DISTRICT III									
		I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				HOLD C104 FOR DIC					
	14. I hereby certify that the foregoing										
	Christine Brock			Title Operations/Regulatory Technician - Sr.							
	0	0		, ,							
	Signature Cluste	ine Keroek		Date 1/28/19							
		THIS SPACE FC	R FEDE	DERAL OR STATE OFFICE USE							
	Approved by						11				
	Ander	ig-		Ti	tle	<i>FE</i>	Date 2/6/19				
	Conditions of approval, if any, are atta	ached. Approval of this notice does not	warrant or c	ertify			/ /				
	that the applicant holds legal or equita entitle the applicant to conduct operat	ble title to those rights in the subject lea ions thereon.	ase which w	O:	ffice	FEO					
		e 43 U.S.C. Section 1212, make it a crin	ne for any pe	erson knowingly and	willfully	y to make to any department or ager	ncy of the United States any				
		ts or representations as to any matter wi			Y						
	(Instruction on page 2)			14000							

.

District I

Form C-102 August 1, 2011

Permit 262911

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II 811 S. First St., Artesia, NM 88210

Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

Energy, Minerals and Natural Resources **Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-045-30274	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
321756	FOGLESON GAS COM	001E
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	5922

10. Surface Location													
UL - Lot	Section		Township	Range	Lot Idn	Feet From	N/S Line		Feet From	E/W Line		County	
1	V	26	30N	11W		955		S	151	5	W		SAN JUAN

			11. Bottom	Hole Locatio	n If Different F	From Surface	9		
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 318.44 S/2			13. Joint or Infi	13. Joint or Infill		ion Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Title: Operation/Regulatory Tech Sr. Date: 1/28/2019							
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: Neale C. Edwards Date of Survey: 4/5/2000 Certificate Number: 6857							

State of New Mexico

Fogelson Gas Com 1E

Section 26-T30N-R11W

API#: 30-045-30274

MV Recompletion Procedure

1/28/2019

Procedure:

- 1. MIRU Service rig and associated equipment, test BOP.
- 2. TOOH w/ 2 3/8" tubing set at 6850'.
- 3. Set bridge plug at approximately 5200' to isolate existing perforations.
- 4. Run Gamma Ray log.
- 5. ND BOP, NU frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Mesa Verde. Estimated interval: MesaVerde as determined by GR log, currently estimated based on offsets at approximately 3784'-5105'.
- 7. Cleanout to isolation plug. Flow test MV.
- 8. Cleanout to PBTD.
- 9. TIH and land production tubing. Get a commingled flow rate.
- 10. Release service rig and turn well over to production.

Hilcorp Energy Company

.

Current Schematic

Well Name: FOGELSON GAS COM #1E

