| | х Э | | | | | | | |
|-----|--|--|---|----------------------|---|---|--------|---------------|
| | m 3160-5 me 2015) UNITED STATES DEPARTMENT OF THE INTERIOR | | | | | FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 | | |
| | BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS | | | | 5. Lease Serial No. 1149IND8486 | | | |
| | Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. | | | | | 6. If Indian, Allottee or Tribe Name | | |
| = | SUBMIT IN TRIPLICATE - Other instructions on page 2 | | | | | 7. If Unit or CA/Agreement, Name and/or No. | | |
| _ | 1. Type of Well □ Oil Well 🖾 Gas Well □ Other | | | | | 8. Well Name and No. GALLEGOS CANYON UNIT 303 | | |
| _ | 2. Name of Operator BP AMERICA PRODUCTION | PATTI CAMP bbell@bpx.com | ppx.com | | 9. API Well No. 30-045-24012 | | | |
| | 3a. Address 380 AIRPORT ROAD DURANGO, CO 81303 | | 3b. Phone No. (include area code) Ph: 970-712-5997 | | 10. Field and Pool or Exploratory Area WEST KUTZ PICTURED CLIFFS | | | |
| - | 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) | | | | | 11. County or Parish, State | | |
| | Sec 33 T29N R12W Mer NMP SENW 1700FNL 1615FWL | | | | | SAN JUAN COUNTY COUNTY, NM | | |
| - | 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, | | | | | , REPORT, OR OTHER DATA | | |
| - | TYPE OF SUBMISSION | | TYPE OF ACTION | | | | | |
| | Notice of Intent | □ Acidize | Deep | Deepen | | □ Production (Start/Resume) | | ater Shut-Off |
| | | Alter Casing | 🗖 Hyd | Hydraulic Fracturing | | □ Reclamation | | ell Integrity |
| 1 | Subsequent Report | Casing Repair | D New | New Construction | | □ Recomplete | | ther |
| p, | Final Abandonment Notice | Change Plans Plug and Abandon Convert to Injection Plug Back | | | | Temporarily Abandon | | |
| · . | | | | | | - | | |
| | 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. | | | | | | | |
| | BP has determined the referenced well has a recomplete potential in the Fruitland Coal formation and requests approval to Temporarily Abandon (TA) the subject well. | | | | | | | |
| | Please see the attached procedure including wellbore diagrams. | | | | | | 101 | 2019 |
| | In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations. | | | | | DIVIN | ICT | 111 |
| | oporations. | | BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS | | | | | |
| | 14. I hereby certify that the foregoing is true and correct. Electronic Submission #456724 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by MARJORIE BROWN on 03/21/2019 () Name (Printed/Typed) PATTI CAMPBELL Title REGULATORY ANALYST | | | | | | | |
| | | | | | | | | |
| : | Signature (Electronic Submission) Date 03/04/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE | | | | | | | |
| : | Approved By Jr Saly_ | | | Title | | | | Date 3 21 19 |
| | Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond | uitable title to those rights in th | es not warrant or ne subject lease | Office FFO | | | | |
| | Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent | | | rson knowingly and | willfully to m | ake to any department of | agency | of the United |
| : | (Instructions on page 2) | | | | | | | |
| | ** OPERA | TOR-SUBMITTED ** (| DPERATOR- | SUBMITTED * | * OPERAT | FOR-SUBMITTED | ** | |

NMOCDA

Ц

BP America

Plug And Abandonment Procedure

GCU 303

1700' FNL & 1615' FWL, Section 33, T29N, R12W

San Juan County, NM / API 30-045-24012

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.
- 2. Check casing, tubing, and Bradenhead pressures.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOP. Function test BOP.
- 5. P/U 4-1/2" bit or casing scraper on 2-3/8" workstring and round trip as deep as possible above top perforation at 1276'.
- P/U 4-1/2" CIBP, RIH and set CIBP at +/- 1226'. Pressure test tubing to 1000 psi. Load hole, and perform MIT test to 560 psi for 2 hours. If casing passes MIT test well can be shut-in and given a T&A designation once sundry has been submitted upon completion of work.
- 7. L/D workstring. N/D BOP, N/U wellhead and shut-in well. R/D and MOL.



Wellbore Diagram

Gallegos Canyon Unit 303 API #: 3004524012 San Juan County, New Mexico

