**PATTERSON-UTI DRILLING COMPANY**

A LIMITED PARTNERSHIP

1512 Larimer Street, Suite 730, Denver, Colorado 80202
303-542-1900 • Fax: 303-542-1903

30-039-27743


June 12, 2005

Rig#741
Huntington
6301 Waterford Blvd.
Oklahoma City Ok. 73118This is to certify that Patterson UTI Drilling, did run deviation surveys at the listed depth on your
Canyon Largo #456 Sec.3T24NR7W.

Depth	Deviation	Depth	Deviation
189'	1¼°	3010'	1¼°
341'	1¼°	3450'	1½°
1341'	1¼°	4101'	3°
1877'	1°	4309'	2½°
2469'	1°	4530'	1¾°

To the best of my knowledge, I swear this information to be true.

Sincerely,



Gary Miller
Area Drilling Manager

State of New Mexico county Rio Arriba

This instrument was acknowledged before me

by Gary Miller

Notary public

My commission expire 5-1-09

88