



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

July 16, 2003

Mr. Sterg Katirgis
Williams Production Company
PO Box 3102
Tulsa OK 74101

Re: Rosa Unit #24, M 32-31N-05W API 30-039-07933

Dear Sterg:

The Bradenhead test on the above well indicates a possible failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before September 15, 2003.

Reference CTP0319642673 on all future correspondence

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File