FORM APPROVED Form 3160-5 UNITED STATES Budget Bureau No. 1001-0135 (November 1994) DEPARTMENT OF THE INTERIOR Expires November 30, 2000 **BUREAU OF LAND MANAGEMENT** Lease Serial No. <u>MMNM035634</u> SUNDRY NOTICES AND REPORTS ON WELLS If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 2003 7. In Unit or CA/Agreement, Name and/or No FIGUEIVED SUBMIT IN TRIPLICATE - Other instructions on revers OIL CONS. DIV. DIST. 3 1. Type of Well Well Name and No. ¥CGRADY, H.B. A 1E 2. Name of Operator XTO ENERGY INC. 9. API Well No. 3a. Address 3b. PhoneNo. (include area code) 30-045-26095 2700 Farmington Ave., Bldg. K. Ste 1 Farmington, NM 87401505 324 1090 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) BASIN FRUITLAND COAL 1000' FSL & 1000' FEL SESE, Sec 14, T27N, R12W 11. County or Parish, State san Juan NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHERDATA 12. TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Fracture Treat Reclamation Well Integrity Alter Casing X | Subsequent Report New Construction Recomplete Other Casing Repair Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or CoommpletedOperation (clearly state all pertinent details, including estimated starting date of any proposed work and approximated uration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final AbandonmentNotices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) XTO Energy Inc. completed P&A of the Fruitland Coal in this well in the following manner: 6/21/03 - 6/26/03: MIRU A-Plus Rig #5 & cmt equip. Notified BLM Sunday morning. Tgd CIBP @ 1710'. Circ hole clean. Spotted balanced plug fr/1710' - 814' w/68 sx cmt. Tgd TOC @ 847'. PT csg to 500 psig. Held OK. Spotted plug #2 fr/576' - surf; good cmt returns. Dug out & cut off WH. Installed dry hole marker w/19 sx cmt. RDMO A-Plus Rig #5. Cut rig anchors. 7/9/03: Reclaimed & seeded location. P&A completed. 70 Farmington, N 14. I hereby certify that the foregoing is true and correct Title

Name(Printed/Typed)
DARRIN STEED REGULATORY SUPERVISOR 7/10/03 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

ACCEPTED FOR RECORD

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.