UNITED STATES FORM APPROVED Form 3160-5 DEPARTMENT OF THE INTERIOR OMB No. 1004-0135 (November, 1996) Expires: July 31, 1996 BUREAU OF LAND MANAGEMENT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS SF-079043 Do not use this form for proposals to drill or to re-enter ar Allottee, or Tribe Name 6. Mundian. abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA. Agreement Designation SUBMIT IN TRIPLICATE- Other Instructions on the reverse side 1. Type of Well Northeast Blanco Unit 8. Well Name and No. X Gas Weil Oil Well Other 2. Name of Operator **NEBU 421** 9. AP Well No. Devon Energy Production Co. L.P. Attn: Kenny Rhoades 3a. Address 3b. Phone No. (include area code) 30-039-24345 10. Field and Pool, or Exploratory Area 1751 Highway 511 Navajo Dam, NM 87419 (505)320-6310 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) **Basin Fruitland Coal** 11. County or Parish, State 215' FSL & 740' FEL , T 30N R. 7W /4, Sec. Latitude Longitude Rio Arriba NM CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Acidize Deepen Production (Start/ Resume) Water Shut-off Altering Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required susegunet reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in anew interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) Devon Energy plans to follow the procedure below to plug and abandon the subject well: MIRU H2S safety company, Service Unit, Pump, Pit and BOPE. Remove POW equipment. 370 Farmington, NN Set cement retainer at 2850'. Pressure test casing to 500 psi. Squeeze below retainer with 100 sx class B cement. Spot 315 sx class B cement to surface. RDMO SU. Set P&A marker and remove all equipment and reclaim location.

14. I hereby certify that the foregoing is true and correct.

Name (Printed/ Typed)

Kenny Rhoades

Company Representative

Signature

Date

Title

Title

Title

Title

Original Signed: Stephen Mason

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitio or fraudulent statements or representations as to any matter within its jurisdiction.