

UNITED STATES  
DEPARTMENT OF INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

2006 JUL 14 AM 7 56

5. Lease Designation and Serial No.  
SF-078771

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation  
ROSA UNIT

8. Well Name and No.  
ROSA UNIT #215

9. API Well No.  
30-039-24394

10. Field and Pool, or Exploratory Area  
BASIN FRUITLAND COAL

11. County or Parish, State  
RIO ARRIBA, NM

1. Type of Well  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
WILLIAMS PRODUCTION COMPANY

3. Address and Telephone No.  
PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
965' FSL & 1565' FWL, SE/4 SW/4 SEC 26-T31N-R06W

SUBMIT IN TRIPLICATE

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

Notice of Intent

☒ Subsequent Report

Final Abandonment

TYPE OF ACTION

Abandonment

Recompletion

Plugging Back

Casing Repair

Altering Casing

Other Pumping Unit & Rod Installation

Change of Plans

New Construction

Non-Routine Fracturing

Water Shut-Off

Conversion to Injection

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

04-19-2006 MIRU, killed with formation wtr. ND xmas tree & NU BOP & work platform. Unlanded tbg & removed tbg hanger. TIH with tbg and tagged fill @ 3240'. NU air pack, broke circ w/ 10 bph air/soap/corrosion inhibitor. Disp 15 bbls wtr, unable to get below 3241', solid like metal. ND w/ air pack. Measured out of hole w/ tbg. TIH w/ 4 3/4" mill on 2 3/8" tbg. Tag fill at 3240'. NU air and power swivel, broke circulation, circulate & rotate @ 3240', unable to make hole, recovered metal shavings. ND air/power swivel. TOOH w/ tbg & mill. MU 2 3/8" mud anchor & "F" nipple, TIH w/ kill string, SDFN.

04-20-2006 Bled and kill w/ form wtr. TIH w/ mud anchor and prod tbg. Land 102 jts 2 3/8", 4.7#, J-55 tbg @ 3239' as follows: mud anchor, 2.28" "F" nipple @ 3212', 101 jts tbg, 10' & 4' pup jts & 1 jt tbg. ND/NU w/ new prod head. RU to run rods & pump. TIH w/ new pump & rods. Spaced pump and fill tbg w/ formation water. Pressure test w/ rig pump at 500 psi. Stroked pump to 500 psi w/ pulling unit. NU pump jack, hung well on ready for production. Turn well to production department, release rig @ 1730 hrs, 4/20/06.

14. I hereby certify that the foregoing is true and correct

Signed Tracy Ross  
Tracy Ross

Title Sr. Production Analyst

Date July 11, 2006

(This space for Federal or State office use)

Approved by \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

JUL 19 2006

FARMINGTON FIELD OFFICE

NMOC