

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

NMSF - 080247

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

RECEIVED

8. Well Name and No.

FLORANCE 96

9. API Well No.

30-045-11756

10. Field and Pool, or Exploratory Area

BLANCO PICTURED CLIFFS

11. County or Parish, State

San Juan, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

BP America Production Company Attn: Kristina Hurts

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-3866

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1550' FNL & 790' FEL Sec. 24 T29N, R09W SENE

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

BP America requested permission to plug and abandon the subject well in March 2006 and permission was granted 5/16/06.

07/25/06 Test casing to 500 PSI witnessed by Ray Espanosa with BLM. Ran a CBL from 2900' to surface, showing good bond up to 450' from surface. Spot #1 Plug 2327'-2900 with 26 SXS, Density 15.80 PPG, Yield 1.150 cu/ft. #2 Plug 1787'-2126' with 13 SXS, Density 15.80 PPG, Yield 1.150 cu/ft. #3 Plug 445'-747' with 9 SXS, Density 16.10 PPG, Yield 1.150 cu/ft. #4 Plug 0'-215' with 60 SXS, Density 15.80 PPG, Yield 1.150 cu/ft. TIH and tag top of cement @ 426'. Shoot holes at 215' to surface.

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Kristina Hurts

Title Regulatory Analyst

Signature

Date 08/01/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

AUG 08 2006

NMOCD

FARMINGTON FIELD OFFICE