

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 100-0135
Expires November 30, 2000

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

JUL 07 2003

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

142060479

6. If Indian, Allottee or Tribe Name

Ute Mountain Ute Tribe

7. If Unit or CA/Agreement, Name and/or No

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC.

3a. Address

2700 Farmington Ave., Bldg. K. Ste 1 Farmington, NM 87401

3b. Phone (include area code)

505-324-1090

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL, 1650' FWL SEC10, T31N, R14W

8. Well Name and No.

UTE MOUNTAIN

TRIBAL D #1

API Well No.

30-045-10918

9. Field and Pool, or Exploratory Area

TEE DOME PARADOX

11. County or Parish, State

SAN JUAN

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximated duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. proposes to temporarily abandon this well per the attached procedure.

SEE ATTACHED
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

DARRIN STEED

Title

REGULATORY SUPERVISOR

Date 7/2/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

(Signature)

ACTING

MINERALS STAFF CHIEF

Date

JUL 15 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OK *[Signature]* 7/2/03

Ute Mountain Tribal D #1
1,650' FNL & 1,650' FWL, Unit F, Sec 10, T-31-N, R-14-W
San Juan County, New Mexico

Formation: Ute Dome Paradox
Production csg: 5-1/2", 10.5#, K-55, csg @ 9,808'. Cmt'd w/500 sx cmt w/4% gel.
Tailed in w/100 sx neat cmt. TOC by TS 7,400'.
Tubing: 258 jts 2-3/8", 4.7#, J-55 tbg, "F" nipple, 1 jt 2-3/8" tbg & MS.
EOT @ 8,306'.
Perforations: 8,240' - 8,350' w/2 JSPF
Current Status: SI
Purpose: Temporary Abandonment.

- 1) Locate and test rig anchors.
- 2) Notify BLM and NMOCD 24 hrs in advance for casing integrity test.
- 3) MIRU pulling unit. ND WH. NU BOP. TOH with 2-3/8" tbg.
- 4) TIH w/CIBP & 2-3/8" tbg. Set CIBP @ 8,184' (csg collars @ 8,157' & 8,198').
- 5) Load casing w/150 BFW. Pressure test casing and RBP to 500 psig for 30 minutes.
Record test on a chart recorder w/a maximum 2 hr clock & 1,000 psig spring, per
NMOCD requirements.
- 6) Roll the hole with 30 gals corrosion inhibitor. TOH & LD 2-3/8" tbg.
- 7) ND BOP. NU WH. RDMO PU.

XTO Energy Inc.

3160

Tribal Lease: 14-20-604-79

Well: Ute Mountain Tribal D #1

Location: 1650' FNL & 1650' FWL

Section 10, T. 31 N., R. 14 W.

San Juan County, New Mexico

CONDITIONS OF APPROVAL

1. Approval for Temporary Abandonment is granted for a period of 12 months and will expire on July 15, 2004.
2. At the conclusion of the 12 month period, please resubmit form 3160-5 for consideration of continued Temporary Abandonment approval.