Form 3160-5 '(November 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

REC		N		
@ O.	^	4	5000	_

FORM APPROVED Budget Bureau No. 100: 0135

JUP 1 5 2003

Expires November 30, 2000

## 5. Lease Serial No.

י אנ		<b>212</b> 000462
	- A - 48-25	700年にもししてもして

SUNDRY NOTICES	AND REPORTS ON WELLS	## 060462
Do not use this form for	proposals to drill or to re-enter an 3160-3 (APD) for such proposal.	If Indian, Allottee or Tribe Name
abandoned well. Use For	######################################	
SUBMIT IN TRIPLICATE	7. If Unit or CA/Agreement, Name and/or	
1. Type of Well Oil X Gas Well Other		8. Well Name and No. UTE INDIANS A #7
2. Name of Operator XTO Energy Inc.		
3a. Address	3b. PhoneNo. (include area code)	9. API Well No.
2700 Farmington Ave., Bldg. K. Ste	30 - 045 - 11049  10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or SurveyDescrip		BASIN DAKOTA
1650' FNL & 1600' FWL UNIT F, SE	C 02, T31N, R14W	
		11. County or Parish, State
		SAN JUAN NM
12. CHECK APPROPR	IATE BOX(ES) TO INDICATE NATUREOF NOTICE, REPORT	OROTHERDATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Acidize Deepen Production	n (Start/Resume) Water Shut-Off
	Alter Casing Fracture Treat Reclamatic	on Well Integrity
Subsequent Report	Casing Repair New Construction Recomple	
		ily Abandon
Final Abandonment Notice		
	Convert to Injection Plug Back Water Dis	posai
<ol> <li>Describe Proposed or CoommpletedOperation(clear If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final AbandonmentN determined that the final site is ready for final inspect</li> </ol>	ly state all pertinent details, including estimated starting date of any proplete horizontally, give subsurface locations and measured and true vertiformed or provide the Bond No. on file with BLM/BIA. Required su the operation results in a multiple completion or recompletion in a netotices shall be filed only after all requirements, including reclamation ion.)	oposed work and approximateduration thereof ical depths of all pertinent markers and zones ibsequent reports shall be filed within 30 day w interval, a Form 3160-4 shall be filed onc n, have been completed, and the operator ha
XTO Energy Inc. proposes to tempo	prarily abandon this well per the attached pro	ocedure.
JUL 2003  FLOORS D  DIST. 3	(V ~ 3	
14. I hereby certify that the foregoing is true and correct	Title	
14. I hereby certify that the foregoing is true and correct Name(Printed/Typed)  DARRIN STEED	REGULATORY SUPERV	ISOR
Warm Wood	Date 7/2/03	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

S'STAFF CHIEF MINERA Con thouse of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. ACTING

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any departmentor agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OK ADM7

## Ute Indians A #7 1,650' FNL & 1,600' FWL, Unit F, Sec 2, T-31-N, R-14-W San Juan County, New Mexico

Formation:

Ute Dome Paradox

Production csg:

5-1/2", 14#, 15.5#, & 17# K-55, csg @ 8,270'. Cmt'd w/150 sx cmt

w/4% gel. Tailed in w/50 sx neat cmt. TOC @ 7,135'.

Casing leak @ 3,815' (11/30/61). Cut off casing @ 4,198'. RIH w/5-1/2" csg bowl & 4,198' of new 5-1/2" 15.5# & 17# csg. DV tool @ 4,168'. Cmt'd w/1,000 sx cmt w/4% gel & 1# MTP/sk.

246 jts 2-3/8", 4.7#, J-55 tbg, "R" nipple, 1 jt 2-3/8" tbg & NC.

EOT @ 7,981'.

Perforations:

6,473' - 7,856' Honnacker Trail (sqz'd 6/9/93)

7,533' - 8,195' Paradox

**Current Status:** 

SI

Purpose:

Tubing:

Temporary Abandonment.

- 1) Locate and test rig anchors.
- 2) Notify BLM and NMOCD 24 hrs in advance for casing integrity test.
- 3) MIRU pulling unit. ND WH. NU BOP. TOH with 2-3/8" tbg, visually inspect.
- 4) TIH w/CIBP & 2-3/8" tbg. Set CIBP @ 7,500'.
- 5) Load casing w/179 BFW. Pressure test casing and CIBP to 500 psig for 30 minutes. Record test on a chart recorder w/a maximum 2 hr clock & 1,000 psig spring, per NMOCD requirements.
- 6) Roll the hole with 35 gals corrosion inhibitor. TOH & LD 2-3/8" tbg.
- 7) ND BOP. NU WH. RDMO PU.

XTO Energy Inc. 3160

Tribal Lease: 14-20-604-62 Well: Ute Indians A #7

Location: 1650' FNL & 1600' FWL

Section 2, T. 31 N., R. 14 W. San Juan County, New Mexico

## **CONDITIONS OF APPROVAL**

- 1. Approval for Temporary Abandonment is granted for a period of 12 months and will expire on July 15, 2004.
- 2. At the conclusion of the 12 month period, please resubmit form 3160-5 for consideration of continued Temporary Abandonment approval.