Submit 3 Copies To Appropriate D Office	istrict	State of 1		Form C-103					
District I	rict I Energy, Minerals and Natural Resources						March 4, 2004 WELL API NO.		
625 N. French Dr., Hobbs, NM 88240 District II						30-045-33633			
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION						5. Indicate T		f Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410						STATE FEE			
District IV Santa Fe, NM 8/503						6. State Oil	& Gas	Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505						E-3150-11			
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DE									
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							Com		
1. Type of Well:							8. Well Number #1E		
Oil Well Gas Well X Other									
2. Name of Operator 9. OGRID Number									
Burlington Resources Oil & Gas Company LP 14538									
3. Address of Operator							10. Pool name or Wildcat		
P.O. Box 4289, Farmington, NM 87499-4289							Basin Dakota		
4. Well Location									
Unit Letter <u>E</u> : 1630 feet from the <u>North</u> line and 815 feet from the <u>West</u> line									
Oint Letter	· <del>-</del>	<u>050</u> 1001	nom mc	Norm	inic and	or nom	uic	West inc	
Section 36		Town	nship 31N	Ra	ange 13W NM	PM San	Juan	County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)									
6017'									
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WO				П	REMEDIAL WORK			ALTERING CASING	
						•			
TEMPORARILY ABANDON	ARILY ABANDON 🔲 CHANGE PLA				COMMENCE DRI	ILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING		MULTIPLE			CASING TEST AN	ND			
COMPLETION					CEMENT JOB				
OTHER:					OTHER: Completi	t: Completion Report			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date									
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion									
or recompletion.									
6/5/06 MIRU Aztec #448. ND WH. NU BOP. PU tbg & mill.TIH w/tbg. Unload well. Break circ w/air mist, M/O DV tool, COUT to PBTD. M/O float collar plus 15'. New PBTD @ 6873'. PT csg to 2500psi for 15mins, ok. TOOH LD tbg & mill. RDMO.									
FBID. W/O Hoat collar plus 13. New FBID (4) 08/3. FI csg to 2500psi for 15mins, OK. TOOH LD tog & mill. KDMO.									
6/8/06 RU Blue Jet Wireline. Ran gauge ring from PBTD @ 6883' to surface. Ran CBL/GR/CCL from 6883' to 6400' and from 5100'									
to TOC @ 4540'. Run GR/CCL from 6883' to surface. RD W/L.									
6/16/06 RU Frac valve. PT valve and csg to 4100 psi/15 minutes. Good test.									
- · ·									
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-									
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.									
SIGNATURE Ama	nda	Sainel	le .	<del></del>	TITLE R	egulatory Ana	lyst	DATE <u>8/10/06</u>	
Type or print name A	manda	Sanchez	E-mail a	ddress: a	sanchez@br-inc.co	m Telephor	ne No.	505-326-9891	
			0						
(This space for State use)	——							W112	
**************************************	/ 01	Pa.			PUTY ON A GAS IN	SPECTOR. DIST	. <b>A</b> I	AUG 15 2006	
APPPROVED BY /- / Illanueva TITLE DEPUTY ON & GAS INSPECTOR, DIST. & DATE DATE									