



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

July 16, 2003

Micki Maben
TIFFANY GAS CO.
PO Box 50
Farmington NM 87499

Re: Bradenhead test

Dear Mrs. Mayben:

The Bradenhead test reports submitted on the following wells indicate no bradenhead valve present. Review Rule 115.B.

To allow proper evaluation of this well, submit a wellhead configuration including the wellhead and casing strings before August 1, 2003

Navajo 18 # A1,	API 30-045-20726✓
Navajo 18 #3,	API 30-045-20299✓
Navajo 18 #4,	API 30-045-20300✓
Navajo 18 #6,	API 30-045-20418✓
Navajo 18 #7,	API 30-045-20468✓
Navajo 18 #8,	API 30-045-20508✓
Navajo 18 #11,	API 30-045-20633✓
Navajo 18 #12,	API 30-045-20698✓
USG Section 18 #52,	API 30-045-27438✓
USG Section 18 #53,	API 30-045-27942✓
USG Section 18 #54,	API 30-045-27943✓
USG Section 18 #55,	API 30-045-27944✓
USG Section 18, #56	API 30-045-27945✓
USG Section 18 #57	API 30-045-20796✓

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File