

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an Abandoned well. Use  
Form 3160-3 (APD) for such proposals

FORM APPROVED  
OMB No. 1004-0135

Expires November 30, 2000

5. Lease Serial No.

NM-03549

6. If Indian, Allottee or tribe Name

7. Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Florance Gas Com L 1

9. API Well No.

30-045-29336

10. Field and Pool, or Exploratory Area

Fruitland Coal

11. County or Parish, State

San Juan County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Company Attn: KRISTINA HURTS

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-3866

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1190' FSL & 1450' FWL SEC. 20 T28N R08W UNIT N

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water shut-Off  
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity  
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Abandon  
☐ Change Plans ☐ Plug and Abandon ☐ Water Disposal  
☐ Injection ☐ Plug Back ☒ Other Perfs added to existing FC formation

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

On 8-11-05 additional perfs were inadvertently added to the existing Fruitland Coal formation in the above mentioned wellbore. Please accept this after the fact subsequent sundry.

TIH & SET RBP @1840'; TEST CSG 3000 PSI OK. TIH w/3.125" GUN & PERF'd FRUITLAND COAL 2110' - 2130' @4 JSPF. TIH & FRAC'd FC w/500 GAL. 15% KCL, DISP w/8 bbls KCL H2O. TIH & DRILLED UP PLUG @1840'. TIH & LANDED TBG @2126'.

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Cherry Hlava

Title

Regulatory Analyst

Signature

*Cherry Hlava*

Date

9/11/2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

SEP 11 2006

NMOCD

FARMINGTON FIELD OFFICE