Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

MDA 701-98-0013

				111271700000
Do not use this form for proposals to drill or reenter an				6. If Indian, Allottee or Tribe Name
abandoned well.	Use Form 3160-3 (API)) for such proposals.	69 7 1	Jicarilla Apache Tribe
				7. If Unit or CA/Agreement, Name and/or No.
SUBMIT IN TRIPL	ICATE - Other instru	uctions on reverse	side	, , , , , , , , , , , , , , , , , , ,
1. Type of Well Of Office and Off				
Oil Well X Gas Well Other				8. Well Name and No.
2. Name of Operator				Jicarilla 29-03-01 #1
Black Hills Gas Resources, Inc. c/o Mike Pippin LLC (Agent)				9. API Well No.
3a. Address		3b. Phone No. (include a	(include area code) 30-039-26663	
3104 N. Sullivan, Farmington, NM 87401		505-327-4573		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Cabresto Canyon Tertiary
1805' FSL & 1870' FEL Unit (J)				AND
Sec. 1, T29N, R3W			Rio Arriba County, New Mexico	
12. CHECK APPROPRIATE BOX	X(ES) TO INDICATE NA	TURE OF NOTICE, REP	ORT, OR OT	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamatio	(Start/Resume) Water Shut-Off n Well Integrity
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other
_	Change Plans	Plug and Abandon	Temporaril	y Abandon
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osal
If the proposal is to deepen directionall Attach the Bond under which the work Following completion of the involved op	y or recomplete horizontally, give will be performed or provide the erations. If the operation results	subsurface locations and measure Bond No. on file with BLM/Bl n a multiple completion or recor	d and true vertice. A. Required sub- npletion in a new	posed work and approximate duration thereof. al depths of all pertinent markers and zones sequent reports shall be filed within 30 days / interval, a Form 3160-4 shall be filed once / have been completed, and the operator has

Black Hills Gas Resources would like to test this well for casing leaks & squeeze with cement, if necessary. The well will then be placed on pump.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

4. I hereby certify that the foregoing is true and correct			
Name (Printed/Typed)	Title		
Mike Pippin	Petroleum Engineer (Agent)		
Signature Miko typnin	Date October 13, 2006		
THIS SP	PACE FOR FEDERAL OR STATE USE		
Approved by	Title f. By. Date 10/17/06		
'onditions of arthoval, if any, are attached. Approval of this notice does in ertify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.			

(Instructions on reverse)

determined that the site is ready for final inspection.)

BLM CONDITIONS OF APPROVAL

WORKOVER AND RECOMPLETION OPERATIONS:

A properly functioning BOP and related equipment must be installed prior to commencing workover and/or recompletion operations.

SURFACE USE OPERATIONS:

The following Stipulations will apply to this well unless a particular Surface Managing Agency or private surface owner has supplied to BLM and operator a contradictory environmental stipulation. The failure of operator to comply with these requirements may result in assessments or penalties pursuant to 43 CFR 3163.1 or 3163.2. A copy of these conditions of approval shall be present on location during construction, drilling and reclamation activity.

An agreement between operator and fee landowner will take precedence over BLM surface stipulations unless (in reference to 43 CFR Part 3160) 1) BLM determines that operator's actions will affect adjacent Federal or Indian surface, or 2) operator does not maintain well area and lease premises in a workmanlike manner with due regard for safety, conservation and appearance, or 3) no such agreement exists, or 4) in the event of well abandonment, minimal Federal restoration requirements will be required.

STANDARD STIPULATIONS: All surface areas disturbed during work-over activities and not in use for production activities will be reseeded. This should occur in the first 90 days after completion of work-over activities.

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.