submitted in lieu of Form 3160-5 UNITED STATES

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	BUREAU OF LAND MANAGEMENT	월 <u></u>	2013 00	
-	Sundry Notices and Reports on Wells		- 2013 007 I T	Pri
1.	Type of Well		070 FAM. 6.1	Lease Number NMSF-078998 Alf Indian, All. or
	GAS			Tribe Name
2.	Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP		7.	Unit Agreement Name San Juan 32-7 Unit
<u> </u>			8.	Well Name & Number
	PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	San Juan 32-7 Unit #17A API Well No.
4.	Location of Well, Footage, Sec., T, R, M			30-045-33832
			10.	Field and Pool
	Surface – Unit O (SWSE), 815' FSL & 1665' FEL, Section Est. BH – Unit P (SESE), 760' FSL & 760' FEL, Section 17			Basin DK & Blanco MV
			11.	County and State San Juan Co., NM
_	X Subsequent Report Plugging Non- Casing Repair Wate			C Other –
13	3. Describe Proposed or Completed Operations			
tl tl b	The well is in the middle of the fairway, therefore loss oal with mud or water in order to set 7" casing into the losses. Drilling the 6-1/4" hole with the coal in the ne hole while drilling. We will handle this water influecause the well is Mesa Verde only, i.e. we don't have the well is directional. The revised depth for the 7" capolumes will change slightly in proportion with the revised	te Lewis. Setting to 6-1/4" interval ux by drilling with to be complete asing would be 3	g 7" casing abo may cause the th mist. We ar ely dry (with air	ve the coal will avoid coal to flow water into e able to drill with mist
	igned Hatsy Clugston	Title <u>Sr.</u>]	Regulatory Specia	list Date <u>10/17/06</u>
A C	This space for Federal or State Office use) PPROVED BY CONDITION OF APPROVAL, if any: tle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any departme e United States any false, fictitious or fraudulent statements or representations as to any matter within its ju	ent or agency of urisdiction	w.	Date 10/20/06