

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2. Name of Operator Pogo Producing Company

3a. Address

P. O. Box 10340, Midland, TX 79702-7340

3b. Phone No. (include area code)

432-685-8100

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

953' FSL & 696' FEL, Section 28, T30N, R13W

5. Lease Serial No.

NMSF-078214

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Ruth #1T

9. API Well No.

30-045-33285

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

TYPE OF ACTION

☐

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☐

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☐

Recomplete

☐

Temporarily Abandon

☐

Water Disposal

☐

Water Shut-Off

☐

Well Integrity

☒

Other Drilling operations

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud & Set Surface Csg - MIRU Chihuahua #201. Spud well @ 08:00 hrs 03/23/06. Drld 8-3/4" hole to 172'. TD reached @ 12:00 hrs 03/23/06. Ran 4 jts 7" 20# J-55 ST&C csg. Landed csg @ 167.18'. Cmt'd w/ 110 sks Type 5 w/ 2% CaCl₂. Circ 33 sks to surface. Plug down @ 15:00 hrs 03/23/06. WOC 24 hrs. Make cut-off. NU WH & BOP. Test BOP & csg to 1000# ok for 30mins.

TD & Production Csg - Drld 6-1/4" hole to 1742'. TD reached @ 15:00 hrs 03/27/06. Logged well w/ Halliburton. Ran 41 jts 4-1/2" 10.5# J-55 ST&C csg. Landed csg @ 1737.12'. Cmt'd w/ 110 sks Type 5 cmt @ 12.5 ppg followed by 70 sks Type 5 @ 15.6 ppg. Plug down @ 15:30 03/28/06. Circ 33 sks to surface. Ran CBL 04/19/06. Test csg to 1500# for 30 mins.


14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Cathy Wright

Title

Sr. Eng Tech

Signature



Date

08/24/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

SEP 07 2006

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOC