In Lieu of Form 3160 (June 1990)

## **UNITED STATES** DEPARTMENT OF INTERIOR **BUREAU OF LAND MANAGEMENT**

300	Š
	<u>(</u> )
5	8
器	S

5.

FORM APPROVED

Budget Bureau No. 1004-0135 Expires: March 31, 1993

Lease Designation and Serial No.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION

SF-078772

	TO DRILL" for permit for such proposals			6. If Indian, Allottee or Tribe Name		
		2002 101 2000	<u> </u>	9 09		
		7000 001 .7.1 I	7.	If Unit or CA, Agreement Designation		
	SUBMIT IN TRIPLICATE	RECEL		ROSA UNIT		
1.	Type of Well	070 FARUH	8	Well Name and No.		
	Oil Well X Gas Well Other	•		ROSA UNIT #331;		
2.	Name of Operator		9.	API Well No.		
	WILLIAMS PRODUCTION COMPANY	<u> </u>		30-039-24880		
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL		
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 2540' FSL & 1720' FWL, NE/4 SW/4 SEC 35-T32N-R06W		11.	County or Parish, State RIO ARRIBA, NM		
Va	CHECK A BROODDIATE DOVAL TO DIDICATE D	ATURE OF NOTICE DEP	OPT 0			

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
•	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	Other Pumping Unit & Rod Installation	Dispose Water	
		(Note: Report results of multiple completion	
		on Well Completion or Recompletion Report	
		and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

08-14-2006 MIRU, bled down & killed tbg w/ produced water. ND w/ xmas tree & NU w/ BOP & working platform. Unlanded tbg & TIH w/ tbg. Tag fill @ 3134', pbtd @ 3141' = 7' coal fill. NU w/ air pack & broke circ w/ 10 bph air/soap/corrosion inhibitor. Displaced 15 bbls formation water w/ air. Circulated coal fill from 3134' to pbtd at 3141'. Circulated wellbore clean & made soap sweeps, ND w/ air pack, TOH w/ 2 3/8" production string tbg, measured out of hole. Recovered 98 singles = 3118'. SDFN.

08-15-2006 240 psi on csg. Bled down through choke manifold. MIRU w/ Dyna Coil equip. Made up 2 3/8" mud anchor w/ 1.78" F-nipple, exp check & TIH w/ same on 2 3/8" prod tbg w/ 1/4" stainless steel chemical tbg strapped to outside of prod tb. NU w/ chem adapted tbg hanger. Landed tbg overall @ 3141' = 1' above pbtd w/ F-nipple @ 3113'. ND w/ BOP & working platform. Rigged out w/ Dyna Coil equip. NU w/ chem adapted companion flange & new prod head. NU w/ air pack. Pumped ahead w/ 3 bbls prod wtr & pumped off expendable check @ 450 psi. ND w/ air pack. Rigged to run rods. TIH w/ new pump & ¾" sucker rods. Dressed 1 ¼" polished rod w/ 1 ½" liner, stuffing box, load cell & rod rotator. Spaced pump & filled tbg w/ form wtr. Press test tbg @ 500 psi w/ circ pump. Stroked pump to 500 psi w/ pulling unit. Hung well on, turn well to production department. RD & release rig, final report.

14.	I hereby certify that the foregoing is true and correct  Signed Tracy Ross	Title Sr. Production Analyst	Date	October 24, 2006	
	(This space for Federal or State office use)				
	Approved by	Title		Date	<del></del>
	Conditions of approval, if any:				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NOV 0 3 2006

