	·				
	Sundry Noti	ces and Reports	on Wells		
				ĭi 1: 26	Lease Number
_			070 Carralant	nn 111-4	NMNM-01614
Тур	pe of Well GAS		070 Farmington	JH, 19 6 ⁄4	If Indian, All. or Tribe Name
			573 74 25 20		
	me of Operator		1600000	7.	Unit Agreement Name
_	URLINGTON		Allo	٨	
	RESOURCES OIL & GAS	50	AUG 2003		
,	RESCONCES OIL & GAS	COMPANY (C)	L COMS DIV. A	8.	Well Name & Number
	iress & Phone No. of Operat		UST a c	4	Thompson #104
PC	D Box 4289, Farmington, NM	87499 (505) 326	وي 9700-	9.	API Well No. 30-045-31575
1. Loc	cation of Well, Footage, Se	C., T, R, M	1/116013	10.	Field and Pool
	B5'FNL, 775'FEL, Sec.34, T-		IPM O O		Basin Fruitland Coa
				11.	County and State San Juan Co, NM
	HECK APPROPRIATE BOX TO IND				
	Notice of Intent _X_ Subsequent Report	Abandonment Recompletic Plugging Ba	on New Non-		Fracturing
13.	X_ Subsequent Report Final Abandonment Describe Proposed or Compl 8/13/03 MIRU. Spud well @	Recompletic Plugging Ba Casing Repa Altering Ca X Other -	on New Non- air Wate Conv 3. Drill to 13 ST&C csg, set Lyash (81 cu.	Routine r Shut o ersion t 3'. Circ @ 133'. ft.). Ci	Fracturing ff o Injection hole clean. Cmtd w/50
	X_ Subsequent Report Final Abandonment Describe Proposed or Compl 8/13/03 MIRU. Spud well @	Recompletic Plugging Ba Casing Repa Altering Ca X Other - Reted Operations 8:30 am 8/13/03 jts 7" 20# J-55 Portland w/20% fla WOC. NU WH. RE	on New Non- air Wate Wate Sing Conv 3. Drill to 13 ST&C csg, set Lyash (81 cu.) C. Rig release	Routine r Shut o ersion t 3'. Circ @ 133'. ft.). Ci d.	Fracturing ff o Injection hole clean. Cmtd w/50
	X_ Subsequent Report Final Abandonment Describe Proposed or Compl 8/13/03 MIRU. Spud well @	Recompletic Plugging Ba Casing Repa Altering Ca X Other - Reted Operations 8:30 am 8/13/03 jts 7" 20# J-55 Portland w/20% fla WOC. NU WH. RE	on New Non- air Wate Wate Sing Conv 3. Drill to 13 ST&C csg, set Lyash (81 cu.) C. Rig release	Routine r Shut o ersion t 3'. Circ @ 133'. ft.). Ci d.	Fracturing ff o Injection hole clean. Cmtd w/50
14.	X_ Subsequent ReportFinal Abandonment Describe Proposed or Compl 8/13/03 MIRU. Spud well @	Recompletic Plugging Ba Casing Repa Altering Ca X Other - eted Operations 8:30 am 8/13/03 jts 7" 20# J-55 cortland w/20% file. WOC. NU WH. RI	on New Non- air Wate Sing Conv B. Drill to 13 ST&C csg, set Lyash (81 cu.) D. Rig release	Routine r Shut o ersion t 3'. Circ @ 133'. ft.). Ci d.	Fracturing ff o Injection hole clean. Cmtd w/50 rc 2 bbls
14. Signed	X_ Subsequent ReportFinal Abandonment Describe Proposed or Compl 8/13/03 MIRU. Spud well @	Recompletic Plugging Ba Casing Repa Altering Ca X Other - eted Operations 8:30 am 8/13/03 jts 7" 20# J-55 Portland w/20% file. WOC. NU WH. RE foregoing is true Title Recompletion	on New Non- air Wate Sing Conv B. Drill to 13 ST&C csg, set Lyash (81 cu.) D. Rig release	Routine r Shut o ersion t 3'. Circ @ 133'. ft.). Ci d.	Fracturing ff o Injection hole clean. Cmtd w/50 rc 2 bbls

submitted in lieu of Form 3160-5

UNITED STATES