Approved by

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would

United States any false, fictitious or fraudulent statements or representations as to any matter witin its jurisdiction.

RCVD JAN19707 OIL COMS. DIV

FORM APPROVED

Uì	NITED STATES
DEPARTM	ENT OF THE INTERIOR
BURFALLO	F LAND MANGEMENT

OMB No. 1004-0135 Expires November 30, 2000 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS 14-20-603-782 Do not use this form for proposals to drill or to re-enter an Abandoned well. Use AM | Find an, Allottee or tribe Name 2M7 JAN 16 Form 3160-3 (APD) for such proposals Navajo Allotttee SUBMIT IN TRIPLICATE - Other instructions on reverse side ECEIVED Unit or CA/Agreement, Name and/or No. 210 FARMING 180 NWM Name and No. Type of Well X Gas Well Other Navajo Allottee GC B 1 Oil Well API Well No. Name of Operator 30-045-06991 **BP America Production Company** Attn: Cherry Hlava 10. Field and Pool, or Exploratory Area 3a. Address 3b. Phone No. (include area code) Mesaverde P.O. Box 3092 Houston, TX 77253 281-366-4081 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State San Juan County, New Mexico 1845' FNL & 1180' FEL Sec 36 T28N R09W 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Water shut-Off Notice of Intent Deepen ☐ Production (Start/Resume) Well Integrity Alter Casing Reclamation Subsequent Report Fracture Treat Final Abandonment Notice Recomplete Abandon Casing Repair Change Plans Plug and Abandon Water Disposal **Additional MV Perfs** Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection. 11/27/2006 RU WIRE LINE- TIH W/3 1/8th " GUN & PERF MENEFEE FORMATION @ 2 JSPF 16.1 GR 18.5 " PENT. WITH .41 HOLE - PERF INTERVAL 4035'-4050' & 4118' -4128' & 4220'-4230' - RIG DOWN PERF. 12/02/06 RU & FRAC w/150,000# BRADY SND @60 bbl./min. 12/12/06 TEST MV @435 MCF FOR 12 hr. I hereby certify that the foregoing is true and correct Title **Regulatory Analyst Cherry Hlava** Name (Printed/typed) 1/9/2007 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Date

JAN 16 2007





Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the