submitted in lieu of Form 3160-5 UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells	2007 JAN 8 PM 4	14	
	The CANADA	REPSE :	5.	Lease Number NMSF-078543
•	Type of Well GAS	970 FARMINI AT L	6.	If Indian, All. or Tribe Name
	Name of Operator		7.	Unit Agreement Name
	ConocoPhillips			San Juan 32-7 Unit
			8.	Well Name & Number
	Address & Phone No. of Operator			San Juan 32-7 Unit 69M
	PO Box 4289, Farmington, NM 87499 (505) 320	6-9700	9.	API Well No.
4 .	Location of Well, Footage, Sec., T, R, M		-	30-045-32439
			10.	Field and Pool
	Unit F (SENW), 1964' FNL & 2505' FWL, Sec	e. 35, T32N, R7W, NMPM		Basin DK/Blanco MV
			11.	County and State
			San Juan Co., NM	
2.	CHECK APPROPRIATE BOX TO INDICATE Type of Submission Type of Action	E NATURE OF NOTICE, RE	PORT, OTHER	DATA
	Notice of Intent Abandonment Recompletion X Subsequent Report Plugging Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection	X Other – Devi	ated Hole Explanation
	13. Describe Proposed or Completed Operation			
О	7/06, Teledrift failed & the hole @ 7" casing settirm Jim Lovato to continue drilling w/ air vertically. mitted & approved before completion was done.	ng depth showed that it deviated Estimated BH location is 2183	3' FNL & 2275' F	
	NSL 55	15 (Dakota only	_ >	
	. I hereby certify that the foregoing is true and	~		
ię	ned Xanahi Xalanda Kandi	is Roland Title Regul	atory Technician	Date: <u>1/04/07</u> .
	nis space for Federal or State Office use)	Title		Date
YE CC	nis space for Federal or State Office use) PROVED BY ONDITION OF APPROVAL, if any: 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to	Title		DateACCEPTED FOR RECORD

NNOCD B- ACCEPTED FOR RECORD

JAN U. g. 2007

EARMINGTON FIELD OFFICE
BY THE SALVETS