

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

5. Lease Designation and Serial No.

NOG-0502-1714

6. If Indian, Allotted or Tribe Name

7. If Unit or CA, Agreement Designation

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Dugan Production Corp.

8. Well Name and No.

Werito Com #1

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325 - 1821

9. API Well No.

30 045 33382

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**1975' FSL & 1905' FEL (NW/4SE/4)
Unit J, Sec. 8, T23N, R9W**

10. Field and Pool, or Exploratory Area

**Basin Dakota (71599)/
Bisti Gallup, South (5860)**

11. County or Parish, State

San Juan, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Plug DK Complete GA
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The Dakota was perforated from 5460'-5480' with six holes. The interval was acidized with 500 gal. 15% HCL acid. This interval was swabbed for 2 days with water and no gas.

Plan to abandon the Dakota by setting a cast iron bridge plug at the Dakota top 5380' and spotting a 50' cement plug on top.

The Gallup interval will be perforated and fractured.

This procedure was approved verbally by Steve Mason, BLM on 1/12/2007.

14. I hereby certify that the foregoing is true and correct

Signed

John Alexander
John Alexander

Vice-President

Date

1/12/2007

This space for Federal or State office use)

Approved by

Original Signed: Stephen Mason

Title

Date

JAN 15 2007

Conditions of approval, if any: