In Lieu of
Form 3160
(June 1990)

1.

3.

UNITED STATES DEPARTMENT OF INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

If Unit or CA, Agreement Designation

SUNDRY NOTICE	AND REPORTS	ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION

5. Lease Designation and Serial No. NMSF-078764

TO DRILL" for permit for such proposals 2007 FEB 12

628 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE Type of Well

Well Name and No. ROSA UNIT #221A Other

RECEIVE

7.

9.

2 Name of Operator

Oil Well X Gas Well

WILLIAMS PRODUCTION COMPANY

30-039-29492 10. Address and Telephone No.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 925' FNL & 220' FWL, NE/4 NW/4 SEC 18-T31N-R05W

PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254

Field and Pool, or Exploratory Area BASIN FRUITLAND COAL

11. County or Parish, State RIO ARRIBA, NM

API Well No.

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
- "	Casing Repair	Water Shut-Off
Final Abandonment	Altering Casing	Conversion to Injection
	Other Install PU	Dispose Water
		(Note: Report results of multiple completion
		on Well Completion or Recompletion Report
		and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-19-2006 MIRU, csg psi 760#. Blow well down to flowback tank, finish rigging up equipment. ND wellhead, NU BOP, RU rig floor, PU tbg tongs & pump water down backside to control well. Function test BOP, pull tbg hanger, PU 2 its tbg RIH check for fill, tagged fill @ 3568', approx 6' of fill. CO to TD @ 3274', secure well & location, freeze protect equipment & SDFN.

12-20-2006 Csg PSI 700#, blow well down to flowback tank. TOOH & tally tbg string. PU, MU & RIH 2-7/8" notched collar, 1jt tbg, 2-7/8 string float, 4' pup jt, 2.28" "F" nipple & standing valve. RIH w/ 2-7/8" tbg, test tbg every 15 stands to 1000 PSI, tbg tested OK. RU & fish standing valve. PU 2 its tbg, tag TD @ 3574', est. circulation w/ 10bph air/mist, 1 gal foamer & ½ gal corrosion inhibitor per 10 bbls produced coal water. CO to TD. TOOH, SDFN.

12-21-2006 Csg psi 620#. Blow well down to flowback tank, RU Dynacoil equipment, RIW w/ BHA, tbg & Dynacoil tbg, ND BOP, land tbg, NU sucker rod wellhead, PU, MU & RIW w/ pump & sucker rods, space out pump & rods. SDFN.

12-22-2006 Csg psi 690#, blow well down to flowback tank, load tbg w/ produced coal water & test to 500 psi, release pressure, stroke pump w/ pulling unit to 500 psi. Tie polished rod to pumping unit. Turn well to production department, release rig.

RCVD FEB14'07 OIL CONS. DIV.

DIST. 3

14.	I hereby certify that the foregoing is true and correct		
	Signed Tracy Ross U	Title Sr. Production Analyst	Date February 8, 2007
	(This space for Federal or State office use)		
	Approved by	Title	Date
	Conditions of approval, if any:		ACCEPTED FOR MANORD
6 00 1 10 1	11000		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Where is TB6 Landed at. Include Next Report.

