In Lieu of UNITED STATES Form 3160 DEPARTMENT OF INTERIOR (June 1990) BUREAU OF LAND MANAGEMENT			FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICE AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals			ease Designation and Serial No.
		6. <u>1</u> I	f Indian, Allottee or Tribe Name
SUBMIT IN T	RIPLICATE	7. I	f Unit or CA, Agreement Designation
Type of Well     Oil Well Gas Well X Other		i -	Well Name and No. ROSA UNIT #260A
2. Name of Operator WILLIAMS PRODUCTION COMPANY		l	API Well No. 10-039-29546
3. Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101	(918) 573-6254	1	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4. Location of Well (Footage, Sec., T., R., M., or 790' FSL & 1960' FEL, SW/4 SE/4 SEC 21	• •	ı	County or Parish, State RIO ARRIBA, NM
CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent  X Subsequent Report	Abandonment Recompletion Plugging Back		Change of Plans New Construction Non-Routine Fracturing
Final Abandonment	Casing Repair Altering Casing Other <u>RIH &amp; land prod tbg, rods &amp; pump, R</u>		Water Shut-Off Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*			
12-13-2006 MIRU, spot rig & equipment. MI & NU w/ flowback tank, MI & spot air pack. Set up w/ rig mast, bled down to flowback tank. ND w/ xmas tree, NU w/ BOP & work platform, function tested BOP. Rigged to pull tbg, unlanded tbg & removed tbg hanger. TDH & tagged fill @ 3250' = 7' fill, TD @ 3257'. NU w/ air pack, broke circ w/ 10 bph air/soap/corrosion inhibitor. Circulated coal fines from 3250' to 3255', stopped solid @ 3255', unable to get below 3255'. Circulated wellbore clean & made soap sweeps, recovered coal fines & light to medium water, hung tbg off @ 3230'. Winterized circ pump & rig equipment.			
12-14-2006 Csg psi 600#. Bled to flowback tank, thawed frozen BOP rams. TOOH w/ 2 7/8" prod tbg, measured & inspected out of hole. Recovered 102 jts 2 7/8" tbg = 3208'. Corrected fill depth = fill was @ 3240', CO to 3245'. PBTD is @ 3245'. MU SN & retrievable standing valve, TIH w/ same on 2 7/8" prod string tbg, wet tested in hole, no leaks. MU & TIH w/ little red retrieving tool, retrieved standing valve, TOH w/ 2 7/8" prod string tbg. Winterized pump & rig equipment & made well safe for night.			
strapped 1/4" stainless steel chem capillary tube to 3243' as follows: 1 jt tbg, 10', 8' & 6' pup jts, 2.28" "head. NU air pack. Pump ahead w/ 3 bbls form w rods. Dressed new polished rod. Spaced pump &	MIRU w/ Dyna Coil equip. Made up 2-7/8" slotted outside of prod tbg. NU w/ chem adapted tbg hange "nipple @ 3214', 100 jts tbg. ND BOP & work platfer, pump off expendable chk at 500#. ND air pack. fill tbg w/ prod wtr. Press test tbg @ 500# w/ rig pu Turn well over to production department, release rig.	er. Landed 1 orm. NU che RU to run ro	01 jts 2-7/8", 6.5#, J-55, 8rd EUE tbg @ m adapted companion flange & new prod ds & pump. TIH w/ new pump & 3/4"
14 Thereby certify that the foregoing is true and			UIL CUNS. DIV.

Signed Tracy Ross Title Sr. Production Analyst Date February 10, 2007

(This space for Federal or State office use)

Approved by \_\_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State of Fargulent statements or representations as to any matter within its jurisdiction.

FARMAGTON PRIED COPYCE