Remove from TA status, MIT

compliant.

Form 3160- 5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR

OMB No. 1004- 0137

BUREAU OF LAND MANAGEMENT		Expires: March 31, 2007
SUNDRY NOTICES AND REP	PORTSON WELZS PM 12:	53 Z ease Serial No. 142006038103
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals € □		 If Indian, Allottee, or Tribe Name NAVAJO TRIBE
SUBMIT IN TRIPLICATE - Other Instruction	s on reverse side	7 If Unit or CA. Agreement Name and/or No.
1. Type of Well Oil Well Gas Well X Other WAT	ER DISPOSAL WELL	8. Well Name and No.
2. Name of Operator		NAVAJO TRIBE 'AR' #8
CHAPARRAL ENERGY L.L.C.		9. API Well No.
3a. Address	b. Phone No. (include area code)	30-045-21482-S1

405-478-8770 × 1197 10. Field and Pool, or Exploratory Area 701 Cedar Lake Blvd., Oklahoma City, OK 73114 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) TOCITO DOME PENN 'D' 11. County or Parish, State NE NW of Sec. 27-26N-18W 660' FNL & 1980' FWL SAN JUAN, NM 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-off Notice of Intent Acidize Production (Start/Resume) Deepen Altering Casing racture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Subsequent Report

Plug and abandon

Temporarily Abandon

Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug back

Well failed MIT and was shutin immediately. Notifilied BLM of TA on 2/16/07. Located rig and MIRU on 2/19/07. POOH with 188 joints 2 3/8 tbg. Found hole in 153rd jt.. SDON. Ran in hole with 188 jts. IPC 2 3/8 tbg with Guiberson XL on-off tool: Latch to pkr at 6077'. Pressured annulus to 1000 psi to test for leaks, found none. Scheduled MIT for 2/21/07. SDON Well passed MIT. Witnessed by Leroy Lee (NNEPA) and Monica Kuehling (NMOCD). Permission granted to resume water disposal. Well no longer is TA, now active SWD.

Inj interval 6209-6236

Change Plans

Convert to Injection

Final Abandonment Notice

SHD-259		
14. I hereby certify that the foregoing is true and correct.		
Name (Printed/ Typed)	Title	
DAVID P. SPENCER	Title	MANAGER OF REGULATORY AFFAIRS
Signature Van Harmer	Date	2/22/2007
THIS SPACE FOR FEDER	RAL OR ST	ATE OFFICE USE
Approved by	Title	Doto
Conditions of approval, if any are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereo	or se Office	ACCEPTED FOR THE CORD

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD