Form 3160- 5 (September 2001)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS ?

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. Expires: January 31,2004

Lease Serial No.		
	SF-047017	В

6. If Indian, Allottee, or Tribe Name

	RCV	FEB2	8'07		
If Unit or CA.	. Agreement Designation				
		~~~			

SUBMIT IN TRIPLICATE - Other Instructions on reverse side				7. If Unit or Ca	A. Agreement Designation OIL CONS. DIV.	
Oil Well X Gas Well	Other			8. Well Name	DIST. 3	
2. Name of Operator				Marie #2		
Chaparral Oil & Gas, Inc				9. API Well No	).	
3a. Address	ress 3b. Phone No. (include area code)		ude area code)	30-045-33540		
P.O. Box 962 Farmington, NM 87499 (505) 486-1701			486-1701	10 Field and P	ool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Basin Fruitland Coal	
				11. County or F	Parish, State	
14	40' FSL & 1390' FEL J, Sec 13,	T-28-N, R-11-W		San Ju	ian County; New Mexico	
12. CHECK APPRO	PRIATE BOX(S) TO INI	DICATE NATURE OF	NOTICE, REPOR			
TYPE OF SUBMISSION		TY	PE OF ACTION			
Notice of Intent	Acidize	Deepen	Production ( St	art/ Resume)	Water Shut-off	
	Altering Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Cther	
	Change Plans	Plug and abandon	Temporarily Al	oandon	Drilling & Completion	
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal			
Describe Proposed or Completed C	meration (clearly state all pertines	ot details including estimated s	tarting date of any propo	sed work and an	provimate duration thereof	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

4/29/2006 07:00 Spudded Well. Drill 8 3/4 surface hole to 145'. Run 7" 20# J-55 surface casing to 142'. Cement with 60 sx Type 5 cement. Circulate to surface. 5/04/06 Drill 6 1/4" hole to 2030'. Run 4-1/2" 10.5# J-55 casing to 2003'. Cement casing with 180 sx Type 5 lead and 70 sx Type 5 tail. Circulate cement to surface. 5/17/06 Perforate Fruitland Coal interval 1852' to 1865' with 4 SPF. 0.38" EHD. Total 52 holes. 5-18-06 Frac Fruitland Coal with 55.8 mgal x -link and 100,820# 20/40 Brady sand. 5/27/06 Test well at 2 mcfd and 43 bwpd.

14.	1 nereby	centry	that the	toregoing i	s true	and correct.
	~ ·		41			

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any are attached. Approval of this notice does not warrant or

Date

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.

