Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Evniree March 31 200

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an including abandoned well. Use Form 3160-3 (APD) for such proposals.			NM 04208 6. If Indian, Allottee or Tribe Name		
	PLICATE- Other instr	ructions on reverse	Side. 0	7. If Unit or	CA/Agreement, Name and/or No.
1. Type of Well Oil Well	Gas Well Other	210 FAP		8. Well Nam	
2. Name of Operator WEST LARGO CORP.			Federal 14 No. 2 9. API Well No.		
3a Address 8801 S. Yale Ave. Suite 240, T	Tulsa, OK 74137-3535	3b. Phone No. (include at 918-492-3239	rea code)	30-045-32518 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)			Basin Fr	uitland Coal
900' FSL, 840' FEL, (SESE) S	ection 14-T28N-R9W, NMPM	ı		11. County o	r Parish, State n, NM
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE	OF NOTICE, RI	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back			Water Shut-Off Well Integrity Other Production Csg Pressure Test
•		, ,	and measured and tru	e vertical depth	rk and approximate duration thereof, s of all pertinent markers and zones.

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

2/9/07: MIRU Antelope S&S. Set 4-1/2" 5,000# frac valve. Pressure test valve and 4-1/2" csg to 3,800 psig, held steady for 20 min. (See test chart attached).

RCVD MAR13'07 OIL CONS. DIV. DIST. 3

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) John P. Garrett	Title	President					
Signature		03/05/2007					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by		Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject les which would entitle the applicant to conduct operations thereon.		Office					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2)

NMOCD 8 3/13 MAR 1 2 2007

EARWINGTON FIELD OFFICE

