					RCVD APR6'0' OIL CONS. DIV DIST. 3	
Form 3160- 5	UNITED STATES				FORM APPROVED	
(September 2001)	DEPARTMENT OF THE INTERIOR				OMB No. 1004- 0135	
	BUREAU OF LAND MANAGEMENT				Expires: January 31,2004	
(September 2001) SU	NDRY NOTICES AND R	EPORTS ON V	VELLS	5. Lease Serial	No. SE-047017 B . 5 7	
	Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If indian, Al	lottee, or Tribe Name	
	RIPEICATE - Other Instru	ctions on reversi	e side	,	A Agreement Designation	
1. Type of Well Oil Well Gas Well Other				210 F 8. Well Name	<u> </u>	
2. Name of Operator					Marie #2	
Chaparral Oil & Gas, Inc				9. API Well No.		
3a. Address		3b. Phone No. (include area code)		30-045-33540		
P.O. Box 962 Fa	(505)	486-1701	10. Field and P	ool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Basin Fruitland Coal		
					11. County or Parish, State	
1440' FSL & 1390' FEL J, Sec 13, T-28-N, R-11-W					uan County, New Mexico	
12. CHECK APPRO	PRIATE BOX(S) TO INDICA	ATE NATURE OF	NOTICE, REPOR	T, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize] Deepen	Production (S	tart/ Resume)	Water Shut-off	
	Altering Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Y Other	
	Change Plans	Plug and abandon	Temporarily A	bandon	Pressure test	
Final Ahandonment Notice	Convert to Injection	Plug back	Water Disposa	ıl	oseina etrinae	

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

04-30-06 08:00 NUWH & BOP. RU TESTER & TEST 7" 20# J-55 SURF CSG TO 600 PSI FOR 30 MIN.

04-30-06 09:00 TEST BOP, KILL LINES, CHOKE LINES & MANIFOLD TO 250 PSI LOW & 1000 PSI HIGH FOR 30 MIN.

05-04-06 10:00 RU KPPS & CMT 4-1/2" 10.5# J-55 R-3 CSG w/ 250 SX TOTAL TYPE 5 CMT & DISPLACE w/ 31.8 BW. BUMP PLUG 750 -1050 PSI. PLUG DOWN 10:16. HOLD 1050 PSI ON CSG 30 MIN & OK. REL PSI & FLOAT HOLD OK.

Reference 3160-5 dated 2-21-07		
14. I hereby certify that the foregoing is true and correct.		
BRAPLEY W. SALZMAN Tit	· AGENT	
Signature Madley 21 Salaman Dat	APRIL 3.	2007
THIS SPACE FOR FEDER	AL OR STATE OFFICE U	SE POSTER VIEW CONTROL
Approved by	Title	Date APR 0 5 2007
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	FARMINGTON PRODUCTICE
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any states any false, fictitiousor fraudulent statements or representations as to any matter within		make any department or agency of the United

(Instructions on reverse)

