

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED
APR 2007

CONS. DIV. DIST. 3

Lease Serial No.

SF - 078415

If Indian, Allottee or tribal Name
2007 APR 28 AM 11:28

If Unit or CA Agreement, Name and/or No.

RECEIVED
BLM

Well Name and No.

Roelofs B 3A

API Well No.

30-045-22365

Field and Pool, or Exploratory Area

Blanco Mesaverde & Pictured Cliffs

County or Parish, State

San Juan County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1060' FNL & 880' FWL SEC 15 T29N R08W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☒ Other Previously Dual Well
DHC 2348AZ

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

4/5/07 CK PRESSURES; 150 SICP; 140 PSI PS - 20 PSI ON VM - 0 PSI BRAIDEN HEAD. ND WH & NU BOP.

4/9/07 TOH w/1 1/4" TBG.

4/10/07 MILL UP D PKR @3086' & CLEAN OUT.

4/13/07 TOH W/ 2 3/8" TBG. CLEAN OUT TO 5578'.

4/20/07 TIH LAND 2 3/8"; j-55; 4.7#TBG @5510'. TEST TBG TO 500 PSI. NIPPLE DN BOP; NIPPLE UP WELL HEAD; TEST TO 1500 PSI.

Well is currently downholecommingling the MV and PC

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 04/23/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or
Certify that the applicant holds legal or equitable title to those rights in the
subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States
any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

APR 27 2007

NMOCD

FARMINGTON FIELD OFFICE
BY *[Signature]*