RCVD APR20'07 OIL CONS. DIV.

FORM APPROVED OMB No. 1016-3133

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Abandoned well. Use Form 3160-3 (APD) for such proposals, SUBMIT IN TRIPLICATE — Other instructions on re- 1. Type of Well Gas Well Other	7. If Unit, or CA/Agreentent; Name and/or No.
2. Name of Operator 9. API Well No. BP America Production Company Attn: Cherry Hlava 30-045-23684	
3a. Address P.O. Box 3092 Houston, TX 77253 3b. Phone No. (include area co	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 950' FNL & 1600' FWL SEC 17 T29N R08W	11. County or Parish, State San Juan County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
Notice of Intent Acidize Acidize Deepen Alter Casing Fracture Tr	Production (Start/Resume) Water shut-Off eat Reclamation Well Integrity
Casing Repair New Cons Change Plans Plug and A	
Change Plans Plug and A	· · · · · · · · · · · · · · · · · · ·
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection. 3/16/07 SICP = 140 psi; SITP = 140 psi. TIH; TAG FILL @4920'. 3/19/07 ND WH & NU BOP; TST BLIND & PIPE RAMS – OK. TOH w/TBG; TIH TO TOP of LINER. 3/20/07 TIH w/BIT & SCRAPER; TAG PBTD. TIH; SET COMPOSITE BP @3750'. 3/21/07 PRES TST CSG TO 500 PSI; RUN CBL GR 3749' TO SURF. TIH; SET PKR @2431'. TST CSG w/4% KCL to 2000 PSI; HELD OK. – RELEASE PKR; LAY DN PKR. TIH w/3.375" GUN & PERF CHACRA 3170' – 3190' & 3300' – 3320' @ 2 JSPF; TOTAL 80 holes. RIG DN. PRESS TST 250 LOW 1500 HIGH – HELD OK. 3/23/07 TIH SET PKR @2471'. PRESS TST FRAC STRING TO 6500 psi – HELD OK. 3/23/07 TIH SET PKR @3035'. PRES ST FRAC STRING TO 6500 psi – HELD OK. 3/29/07 TIH; SET PKR @3035'. PRES TST DN ANNULUS TO 500 psi – HELD OK. PRES TST LINES & PMP INTO CHACRA PERF w/5 bbis 2% KCL. INT. PRESS = 900 PMP ACID PRESS STOPPED DISPLCE & LET ACID SOAK & DISPCE w/18 bbis WTR; UN SET PKR – TOH. PRES TST 1500/250 – HELD OK. TIH; SET PKR & LOAD TBG & TST FRAC STR TO 6500 psi & TST ANN to 500 psi – HELD OK. 3/30/07 TIH; FRAC CHACRA w/149,403 Ib PROPNET. FLW TO PIT ON 1/8" CK.	
14. I hereby certify that the foregoing is true and correct Name (Printed/typed)	
Cherry Hlava	Title Regulatory Analyst
Signature Chery Hava Date 04/17/2007	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by	Title Date APR 1 8 2007
Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office FARMANOTON PIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for are second knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter with the statements of the United States any false, fictitious or fraudulent statements or representations as to any matter with the statements of the United States and States are statements or representations.

RIDDLE F LS 1A 30-045-23684

4/3/07 TOH w/ FRAC STRING & LAY DN PACKER.

4/4/07 400# PRESSURE; BLW DN. BLW BACK FRAC FLUID. TIH to TOP OF LINER; BRAKE CIRC.

4/5/07 PRES 340# BLW DN. CLEAN OUT TO 3430'.

4/6/07 TIH; SET PKR @3130'. RU FLW TST; TST on 1/2" CK

4/9/07 UNSEAT PKR & TOH w/PRK. TIH TAG FILL @3336'. CLEAN OUT.

4/10/07 TIH DRILL OUT BP @3430'. TIH DRILL OUT CBP @3750'.

4/11/07 CHECK WELL PSI 0# ON TBG. 410# ON CSG. TAG FILL @4889'. C/O WELL.

4/12/07 PRESS 150# CSG; TBG 0#. TIH LAND 2 3/8" TBG @4704'.

Please approve & sind to NMOCD