


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-129  
Revised June 10, 2003

Submit 3 Copies to appropriate  
District Office

NFO Permit No. \_\_\_\_\_  
(For Division Use Only)

## APPLICATION FOR EXCEPTION TO NO-FLARE RULE 306

(See Rule 306 and Rule 1129)

30-015-30409

A. Applicant Devon Energy Production Company, L.P.,  
whose address is 20 North Broadway, Oklahoma City, Oklahoma 73102-8260,  
hereby requests an exception to Rule 306 for 60 days \_\_\_\_\_ days or until

\_\_\_\_\_, Yr \_\_\_\_\_, for the following described tank battery (or LACT):

Name of Lease Logan 35 B Federal 9 Name of Pool Red Lake; Queen-Grayburg-San Andres-Glorieta-Yeso, NE

Location of Battery: Unit Letter O Section 35 Township 17S Range 27E

Number of wells producing into battery 12

B. Based upon oil production of 70 barrels per day, the estimated \* volume  
of gas to be flared is 110 MCF; Value \$4105.00 per day.

C. Name and location of nearest gas gathering facility:

N/A

D. Distance N/A Estimated cost of connection N/A

D. This exception is requested for the following reasons:

Due to a down compressor, the line pressures has caused a production loss of 70 BOPD and 100 mcf.

### OPERATOR

I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

Signature \_\_\_\_\_

Printed Name Norvella Adams  
& Title Senior Staff Engineering Technician

E-mail Address norvella.adams@dvn.com

Date 4/16/07 Telephone No. (405) 552-8198

### OIL CONSERVATION DIVISION

Approved Until 6/16/07

By Miki Benavon

Title Field Supervisor

Date MAY 11 2007

\* Gas-Oil ratio test may be required to verify estimated gas volume.