

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-045-31138
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator XTO ENERGY INC.		6. State Oil & Gas Lease No.
Address of Operator 2700 FARMINGTON AVE, SUITE K-1, FARMINGTON, NM 87401		7. Lease Name or Unit Agreement Name RIDDLE GAS COM A
4. Well Location Unit Letter <u>G</u> ; 2110 feet from the <u>NORTH</u> line and 1580 feet from the <u>SOUTH</u> line Section <u>09</u> Township <u>27N</u> Range <u>09W</u> NMPM <u>SAN JUAN</u> County		8. Well Number #1R
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6212' GL		9. OGRID Number 167067
		10. Pool name or Wildcat OTERO CHACRA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: RECOMPLETION <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU PU. TOH w/tbg. TIH w/tbg & set CIBP @ 3420'. Pressure tested CIBP to 2000 psig. Did not hold. RU WL trk. RIH w/CIBP & set @ 3418'. Pressure tested CIBP to 2500 psig. Held OK. Perf'd Chacra fr/3167' - 3332', 0.37" dia, 25 holes. Acidized w/1000 gals 7.5% NEFE HCl acid. Frac'd w/50,120 gals 70Q N2 foamed 30# linear gelled 2% KCl wtr w/73,865# 20/40 Brady sand and 20,000# 20/40 Super LC RCS. CO well w/AFU to CIBP @ 3418'. TIH w/prod tbg. The Dakota and Mesaverde formations are hut in pending evaluation of the Chacra. Plans are to DHC the Dakota, Mesaverde and Chacra at a later date.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Darin Steel TITLE REGULATORY SUPERVISOR DATE 9/3/03
Type or print name Telephone No.

(This space for State use)

APPROVED BY [Signature] TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 9 DATE SEP 9 2003
Conditions of approval, if any: