In Lieu of	
Form 3160	-4
(June 1990)	

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No 1004-0135 Expires: March 31, 1993

Lease Designation and Scrial No

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

FM 9 44

5.

If Indian Allottee or Tribe Nan

NMSF-078769

		COUL OUT TO	6	If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICATE	OTO FARMINGT	MA KE	If Unit or CA, Agreement Designation
1.	Type of Well Oil Well X Gas Well Other		8.	Well Name and No. ROSA UNIT #146B
2	Name of Operator WILLIAMS PRODUCTION COMPANY	`	9.	API Well No. 30-039-29833
3	Address and Telephone No PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10.	Field and Pool, or Exploratory Arca BLANCO MV/ BASIN DK
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 800' FWL, NW/4 SW/4 SEC 28-T31N-R05W		11.	County or Parish, State RIO ARRIBA, NM
	CHECK APPROPRIATE BOX(s) TO INDICATI	E NATURE OF NOTICE, REP	ORT, OR O	THER DATA

7	TYPE OF SUBMISSION	TYPE OF ACTION		
?	Notice of Intent	Abandonment	Change of Plans	
		Recompletion	New Construction	
	X Subsequent Report	Plugging Back	Non-Routine Fracturing	
		Casing Repair	Water Shut-Off	
	Final Abandonment	Altering Casing	Conversion to Injection	
		Other Set surface csg	Dispose Water	
			(Note Report results of multiple completion	
			on Well Completion or Recompletion Report	
			and Log form)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

O7-16-2007 Drill 14 ¾" surface hole from 0' to 335' (TD surface hole @ 1730 hrs, 7/15/07). Circ & cond mud for 10 ¾" surface csg. TOOH, LD bit, bit sub & shock sub. RU csg crew & run 9 5/8" surface csg & land @ 326' shoe depth. Guide shoe + 1 jt csg + insert float + 6 jts csg + landing joint = 326' shoe depth, 7 jts, 10 ¾", 45.5#, K-55, ST&C, Range 3, LSS csg = 307'. Circ csg, RD casers & RU cementers. Cmt 10 ¾" csg @ 326', shoe depth, single slurry cmt job, 20 bbls fresh water spacer, 314 sxs Type III cmt + 2% CaCl-2 + 1% Pheno Seal + 22.8 bbl water = 50.64 bbl slurry @ 14.5 PPG. Displace w/ 26.6 bbl water, bump plug @ 560 psi, PD @ 22:00 hrs, check float, not holding, SI w/ 80 psi, 25 bbl cmt returns to surface (TOC on surface csg @ surface). RD cementers & WOC. LD landing jt & make up 11" WH, NU BOP & related equip.

07-17-2007 Finish NU BOP & related equip, test BOP & related equip, low test to 250 psi for 5 min & high test to 2000 psi for 10 min, test 10 ¾" csg to 1500 psi for 30 min, all tested good. Cut 120' drlg line, chain off BOP, install flow nipple & 2" fittings in WH for cmt lines. TIH w/ DC's out of derrick, tag top of cmt @ 267'. Drlg cmt, insert float, cmt, guide shoe from 267' to 326', CO from 326' to 335'. Drill 9 7/8" hole from 335' to 371'. TOOH install float in bit sub, TIH & PU Kelly. Drill 9 7/8" hole from 371' to 787'.

OIL CONS. DIV. DIST. 3

14	I hereby certify that the foregoing is true and correct				
	Signed Wacy Ross Tracy Ross	Title Sr. Production Analyst	Date	July 20,	²⁰⁰⁷ ACCEPTED FOR MECORD
	(This space for Federal or State office use)				JUL 2 5 2007
	Approved by	Title		Date	
	Conditions of approval, if any:				FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, lictuious or fraudulent statements or representations as to any matter within its jurisdiction