Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED							
· OMB No	1004-0135						
Charles In	h 31 1006						

5. Lease Serial No.

NMSF79484A & Fee Surface

6.	If Indian,	Allottee	or Tribe	Name
----	------------	----------	----------	------

abandoned well.	Use Form 3160-3 (APD) fo	or su	ch proposal:	s.	-211	7	1111 25			
						7.		A/Agreer	nent/Mame and/or No.	
SUBMIT IN TRIPLICATE - Other instructions on reverse side						RECEIVED				
1. Type of Well					21		ar itil	·		
Oil Well X Gas Well	Other					8. Well Name and No. 1M				
2. Name of Operator						7	MANY C	ANYO	NS 30-04-12 #124	
Black Hills Gas Resources	, Inc. c/o Mike Pip	pin l	LLC (Agent)		9.	9. API Well No.			
3a. Address 3b. Phone No. (include area code)					code)	7	30-039-29968			
3104 N. Sullivan, Farmingto	on, NM 87401 50	05-32	27-4573			10.	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						Ea	East Blanco Pictured Cliffs			
2535' FNL & 135' FEL Unit I	-1					AN	AND			
Sec. 12, T30N, R04W						D:		<u> </u>	. N N. A	
						KI	o Arriba	County	, New Mexico	
12. CHECK APPROPRIATE BOX	K(ES) TO INDICATE NATUR	E OF	NOTICE, RE	EPORT	r, or ot	THE	R DATA			
TYPE OF SUBMISSION	TYPE OF ACTION									
Notice of Intent	Acidize	Dee	pen Production (Start/Resume) Water Shut-Off ture Treat Reclamation Well Integrity							
Subsequent Report	Casing Repair Change Plans	-	w Construction Recomplete To Other Spud & Surface g and Abandon Temporarily Abandon							
Final Abandonment Notice	Convert to Injection] Plug	g Back		Vater Disp	osal				
If the proposal is to deepen directionally or recomplete honzomally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once. Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 7/13/07. Spud well. Drill 12-1/4" hole to 318'. Ran 9-5/8" 36# J-55 csg & set @ 318'. Cmt w/350 sks (413 cf) Type V cmt w/2% CaCl & 1/4# polyflake. Circ 22 bbls cmt to surface. Pressure test casing to 1000 psi -OK. Pressure test witnessed by Cliff Ollman with the BLM.										
								7	ACCEPTED FOR RECORD	
									JUL 2 6 2007	
								1	FARMINGTON FIELD OFFICE BY TO SALVETS	
14. I hereby certify that the foregoing	is true and correct							k"(BY TO SAIVETS VUJULBU U 7	
Name (Printed/Typed)	o duo dila oblicor	Title	е							
Mike	Pippin	l		F	Petroleu	ım l	Engineer	(Agen	N CONS. DIV.	
Signature M. M.	Signature Date July 25, 2007									
THIS SPACE FOR FEDERAL OR STATE USE										
Approved by			Title			//	Date			
Conditions of approval, it am, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct	table title to those rights in the subject		Office				4			

(Instructions on reverse)

fraudulent statements or representations as to any matter within its jurisdiction.



Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or