

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other Instructions on reverse side.

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Black Hills Gas Resources, Inc.

3a. Address
P.O. Box 249 Bloomfield, NM 87413

3b. Phone No. (include area code)
505-634-1111

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
**1190' FSL & 1081' FWL Unit M
Sec 22, T30N, R3W**

5. Lease Serial No.
Contract 462

6. Indian, Plantee, or Tribe Name
Jicarilla Apache Tribe

7. If Unit or CA. Agreement Name and/or No.

8. Well Name and No.

Jicarilla 462 #1

9. API Well No.

30-039-24110

10. Field and Pool, or Exploratory Area

East Blanco, Pictured Cliffs

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources has temporarily abandoned this well as follows; a wireline-set CIBP was set @ 1120' 7-19-2007. The mechanical integrity test was performed 7-25-2007. The casing was pressure tested to an initial pressure of 550 psi, after 30 min the pressure was 540 psi. The MIT was witnessed by Shelly Cowden (NMOCD) and Waymore Callado (JIC O&G BLM). TA approved var: 8/1/08

RCVD AUG2'07

OIL CONS. DIV.
DIST. 3

NMOCD TA expires 7/25/2012

14. I hereby certify that the foregoing is true and correct.

Name (Printed/ Typed)

Loren Diede

Title

Consultant (Agent)

Signature

Date

26-Jul-07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD