In Lieu of	
Form 3160)
(Tune 1990	'n

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expirés: March 31, 1993

STINIDAY NOTICE	AND DEDODTE	ONIMELI	
STIMING NOTE OF	ANDERDORIS	(1 N VA/ F= 1)	•

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

Lease Designation and Serial No NMSF-078764: 19

6. PEULITEI)

		BIM Franksh
	SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation Rosa Unit
1.	Type of Well Oil Well X Gas Well Other	8. Well Name and No Rosa Unit #13B
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	9. API Well No. 30-039-29834
3.	Address and Telephone No PO Box 640 Aztec, NM 87410-0640	10. Field and Pool, or Exploratory Area BLANCO MV/BASIN DK
4.	Location of Well (Footage, Sec., T, R., M., or Survey Description) 595' FNL & 645' FEL Sec 31, T31N, R5W NMPM	11. County or Parish, State Rio Arriba, New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF	ACTION
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
• •	Casing Repair	Water Shut-Off
Final Abandonment	Altering Casing	Conversion to Injection
	X Other Multiple zone completion	Dispose Water
t		(Note: Report results of multiple completion
		on Well Completion or Recompletion Report
		and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Williams Production Company, LLC. hereby requests authority to drill this as a Mesa Verde/Dakota dual as per attached plat and Operations plan.

RCVD AUG 23 '07 OIL CONS. DIV. DIST. 3

14	I hereby certify that the foregoing is true and correct	_
	Signed Larry Higgins Title Drilling C.O.M. Date 8-13-07	
	(This space for Federal or State office use)	
	Approved by Date 8/21/07	
	Conditions of approval, if any:	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I 1625 N. French Dr., Hobbs, NM 88240

APT Number

State of New Mexico Energy, Minerals & Natural Resources Department

District II 1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

Pool Code

District IV 1220 S St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-102 Revised October 12, 2005 Instructions on back Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

RCVD AUG 23 '07

AMENDED REPORT


ITL CONS. DIV.

WELL LOCATION AND ACREAGE DEDICATION PLAT 30-039-29834 DIST. 3

Pool Name

30.03	9-2	R-29834 72319 / 71599 BLANCO MESAVERDE / BASIN DAKOTA								
*Property			⁵ Property Name						⁵Well Number	
17033	3				ROSA	UNIT				13B
'OGRID N	10				*Operato	r Name	 		*Elevation	
12078	2	WILLIAMS PRODUCTION COMPANY					6536 '			
	¹⁰ Surface Location									
UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/Wes	t line	County
A	31	31N _	5W		595	NORTH	645	EAS	ST	RIO ARRIBA
	¹¹ Bottom Hole Location If Different From Surface						J			
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/Wes	t line	County
¹² Dedicated Acres 232.89 Acres - (N/2)				¹³ Joint or Infill	³⁴ Consolidation Code	¹⁵ Order No.				

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom-hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral contract with a mineral con or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. Date Signatúre ARRY Printed Name 18 SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief Survey Date JANUARY 24, 2006 Signature and Seal of Professional Surveyor SE UN MEXICO MEXIC NEW 15269 8 SAME STEEL AND ESSIONAL

Certificate Number

15269



WILLIAMS PRODUCTION COMPANY

Operations Plan

(Note: This procedure will be adjusted on site based upon actual conditions)

•

DATE:

8/8/2007

FIELD:

Basin DK/BlancoMV

WELL NAME:

Rosa #13B

SURFACE:

BLM

BH LOCATION:

NENE Sec 31-31N-5W

MINERALS:

BLM

ELEVATION:

6,536' GR

Rio Arriba, NM

LEASE#

SF-078764

MEASURED DEPTH: 8,115'

0.1151

I. I. GEOLOGY:

Surface formation - San Jose

A. FORMATION TOPS: (KB)

Name	MD	Name	MD
Ojo Alamo	2,640	Menefee	5,590
Kirtland	2,775	Point Lookout	5,800
Fruitland	3,145	Mancos	6,130
Pictured Cliffs	3,370	Gallup	7,110
Lewis	3,650	Greenhorn	7,825
Cliff House	5,530	Graneros	7,875
		Dakota	8,000
		TD	8,115

- B. MUD LOGGING PROGRAM: Mudlogger on location at 100' above Gallup SS to TD. Mud logger to pick TD.
- C. LOGGING PROGRAM: HRI from surface casing to TD. SDL\DSN\DSEN over zones of interest.
- **D.** <u>NATURAL GAUGES:</u> Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.

II. DRILLING

- A. MUD PROGRAM: Clear water with benex to 7-5/8" casing point. Convert to a LSND mud to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses. Use air w/Air Hammer from 7-5/8in. csg.to TD.
- B. <u>BOP TESTING</u>: While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the BOPE will be tested to 250 psi (Low) for 5 minutes and 1500 psi (High) for 10 minutes. Utilize a BOPE Testing Unit with a recording chart and appropriate test plug for testing. The drum brakes will be inspected and tested each tour. All tests and inspections will be recorded in the tour book as to time and results.

A. CASING PROGRAM:

CASING TYPE	OH SIZE (IN)	DEPTH (MD) (FT)	CASING SIZE (IN)	WEIGHT(LB)	GRADE
Surface	14 3/4	300	10 3/4	40.5	K-55
Intermediate	9 7/8	3,845	7 5/8	26.4	K-55
Longstring	6 3/4	8,115	5 1/2	17	N-80

B. FLOAT EQUIPMENT:

- 1. <u>SURFACE CASING:</u> 10 3/4" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (4) joints of Surface Casing.
- 2. <u>INTERMEDIATE CASING:</u> 7 5/8" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install (1) Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (3) joints to 2,500 ft. Run (1) Turbulent centralizer at 2,700 ft., 2,500 ft., 2,300ft., 2,000ft., 1,500 ft., and 1,000 ft. (NTL-FRA 90-1).
- 3. <u>PRODUCTION LINER / CASING:</u> 5-1/2" whirler type cement nose guide shoe with a latch collar on top of 20' bottom joint. Place marker joint above 5,400'. Place centralizers as needed across selected production intervals.

C. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- 1. <u>SURFACE</u>: Slurry: <u>255sx</u> (356 cu.ft.) of "Type III" + 2% CaCl₂ + ¼ # of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). The 100% excess should circulate cement to the surface. WOC 12 hours. Test csg to 1500psi.
- 2. INTERMEDIATE: Lead 660 sx (1,374) cu.ft.) of "Premium Light with 8% gel and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail 100 sx (139cu.ft.) of "Type III" with 1/4# cello-flake/sk, (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.). Use 100% excess in Lead Slurry to circulate to surface. No excess in Tail Slurry. Total volume = 1,512 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.
- 3. PRODUCTION CASING: 10 bbl Gelled Water space. Cement: 205 sx (442 ft³) of Premium Light HS + 1% FL-52 + .2% CD-32, 0.1% R-3, 3 #/sk CSE, ¼ #/sk cello flake and 4% Phenoseal. (Yield = 2.15 ft³/sk, Weight = 12.3 #/gal.). Displace cement at a minimum of 8 BPM. The 20% excess in slurry should cover 100 ft into intermediate casing. Total volume 438ft³. WOC 12 hours

IV. IV COMPLETION

A. CBL

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement not circulated to surface..

B. PRESSURE TEST

1. Pressure test 5-1/2" casing to 6000 psi max, hold at 1500 psi for 30 minutes.

C. STIMULATION

- 1. Stimulate Dakota with approximately 10,000# of LiteProp 108™ sand in slick water..
- 2. Isolate Dakota with a RBP.
- 3. Stimulate Point Lookout with approximately 9300# of 14/30 LiteProp™ in slick water.
- 4. Isolate Point Lookout with a RBP.
- 5. Perforate the Menefee/Cliff House as determined from the open hole logs.
- 6. Stimulate with approximately 9300# of 14/30 LiteProp™ in slick water.
- 7. Test each zone before removing bridge plugs.

D. RUNNING TUBING

- 1. <u>Dakota</u>: Run 2-1/16", 3.25#, J-55, IJ tubing with 1/2 mule shoe on bottom, SN with pump-out plug on top of adeem joint and 5 Seal Units. Land tubing approximately 100' below top Dakota perf.
- 2. <u>Mesa Verde:</u> Run 2-1/16", 2.9#, J-55, EUE tubing with a SN (1.91" ID) on top of bottom joint. Land tubing approximately 25' above the bottom Point Lookout perforations.

Gary Sizemore

Sr. Drilling Engineer,