

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

1. **Type of Well**
GAS

RECEIVED

SEP 10 2007

Bureau of Land Management
Farmington Field Office

2. **Name of Operator**
CDX RIO, LLC

5. **Lease Number**
Jicarilla Contract 110
6. **If Indian, All. Or
Tribe Name**
Jicarilla Apache
7. **Unit Agreement Name**

3. **Address & Phone No. of Operator**

2010 Afton Place, Farmington, New Mexico 87401 (505) 326-3003

8. **Well Name & Number**

Jicarilla A #2E
9. **API Well No.**

4. **Location of Well, Footage, Sec., T, R, M**

1120'FSL, 1520'FEL, Sec.18, T-26-N, R-5-W, NMPM

30-039-22581
10. **Field and Pool**

Tapacito Gal/Basin DK
11. **County and State**

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment <input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion <input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging <input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair <input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing <input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other <input type="checkbox"/> Tubing repair

RCVD SEP 14 '07
OIL CONS. DIV.
DIST. 3

13. Describe Proposed or Completed Operations

8-22-07 MIRU. SDON.
8-23-07 TOO H w/rods & pump. ND WH. NU BOP. TIH, tag up @ 7533'. TOO H w/2 3/8" tbg. TIH w/bit & csg scraper. SDON.
8-24-07 Tag up w/bit & csg scraper @ 7538'. Blow well & CO. to PBTD @ 7553'. SD for weekend.
8-27-07 Blow well & CO. SDON.
8-28-07 Blow well & CO. TOO H w/bit & csg scraper. TIH w/CIBP & pkr. SDON.
8-29-07 Set CIBP @ 7536'. Set pkr @ 7035'. Load tbg w/wtr. Establish injection. Pump 1500 gal 15% HCl down tbg. Displace w/45 bbl wtr. Release pkr. Reset CIBP @ 6818'. Reset pkr @ 6586'. Load tbg w/wtr. Attempt to establish injection. Reset CIBP @ 6945'. Reset pkr @ 6524'. Load tbg w/wtr. Establish injection. Pump 1500 gal 15% HCl. Displace w/wtr. Blow well & CO. SDON.
8-30-07 TOO H. TIH w/retrieving tools. Release pkr & CIBP. TOO H. SD for holiday.
9-4-07 TIH w/239 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 7491'. PT tbg to 1000 psi, OK. ND BOP. NU WH. TIH w/207 3/4" rods, 88 7/8" rods & pump. Load tbg w/wtr. PT tbg & pump to 1000 psi, OK. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Oltmanns Title Agent Date 9-6-07

ACCEPTED FOR RECORD

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date SEP 12 2007

CONDITION OF APPROVAL, if any:

FARMINGTON FIELD OFFICE