## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM A	PPROVEI		
OMB No.	1004-013		

Lease Serial No.

OMB N	o. 1004	-0135
Expires: No	vember	30, 2000

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SF-079162
6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.			]	リコア	VEIA EIA		
SUBMIT IN TRIPLICATE - Other Instructions on reverse side  1. Type of Well		7. If Unit or CA/A	Agreement, Name and/o	or No.			
Oil Well X Gas Well Other			8. Well Name and	No. sureau of	Land Management		
2. Name of Operator			MKL 12	Famin	gton Field Office		
			9. API Well No.				
3a. Address Suite 600 3b. Phone No (include area code)			30-039-06574				
14000 QUAIL SPGS PKWY, OKLA CITY, OK 73134 405-749-1300			)	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				South Blanco			
				11. County or Parish, State			
1760' FSL & 880' FWL, NW SW, Sec. 8-26N-7W			San Juan, NM				
12. CHECK APPROPRIATE BO	X(ES) TO INDICAT	E NATURE OF N	OTICE, REPO				
TYPE OF SUBMISSION			OF ACTION				
Notice of Intent	Acidize	Deepen		on (Start/Resume) Water Shut-Off			
	Altering Casing	Fracture Treat	Reclamation	· }	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomplete		Other		
	Change Plans X	Plug and Abandon	Temporarily A	bandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	ıl			
Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  6/12/07 P&A'd witnessed by BLM rep Mike Wade, approval given to skip plug #1. Set cmt. Retainer @ 1237'.  Mix & pump 40 sks 14.8#, 1.32 yld., 52.8 cf/sk., type 3 cmt., flush cmt. To EOT. Pump 5 sks below retainer. Cmt. F/1237' to 904'. POOH LD tbg to 411'. Mix & pump 23 sks. 14.8#, 1.32 yld., 30.36 cf/sk, type 3 cmt. to 193'. Cmt. F/411' - 193'. Shot 3 holes @ 143'. Mix & pump 65 sks 14.8#, 1.32 yld., 85.8 cf/sk, type 3 cmt. f/143' to surface. Cut off well head & install dry hole marker. Clean location.  **RCVD OCT 2 '07**  OIL CONS. DIV.  DIST. 3							
14. I hereby certify that the foregoing is true and co	orrect		1				
Carla Christian			Title	Supervisor	Regulatory Rep	oorts	
Signature Cula Wustan Date				September 26, 2007			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by			Title		Dat	e	
Conditions of approval, if any, are attached. A	pproval of this notice doe	s not warrant or				<u> </u>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

OCT 0 2 2007



certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.