Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION		30-045-11180
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE FEE S  6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	20 S. St. Francis Dr., Santa Fe, NM		o. State on & Gas Lease Ivo.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			State Com
PROPOSALS.)  1. Type of Well:		8. Well Number	
Oil Well Gas Well X Other		#9	
2. Name of Operator		9. OGRID Number	
ConocoPhillips Company  3. Address of Operator		14538 10. Pool name or Wildcat	
P.O. Box 4289, Farmington, NM 87499-4289		Blanco Mesaverde	
4. Well Location			
Unit Letter A: 990 feet from the North line and 990' feet from the East line			
Section 36 Township 32N Range 11W NMPM San Juan County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Elevation (Snow whether DR, RKB, R1, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR			BSEQUENT REPORT OF:  RK
FERI ONW REMEDIAL WORK	_	HEWEDIAL WO	THE PERSONNEL PROPERTY OF THE PERSONNEL PROP
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF	RILLING OPNS.□ PLUG AND □ ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND 🗆 RCVD (130 '07
	COMPLETION	CEMENT JOB	OIL CONS. DIV.
OTHER:		OTHER: Tubing	Repair 🗵 DIST. 3
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE BULE 1103. For Multiple Completions. Attach wellboarding on the proposed completion.			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
10/9/07 MIRU AWS 746. RU WL & set DW Plug @ 5235' & 3 slip stops @ 5227'. ND WH & NU BOP, PT-OK. RIH & tagged fill @ 5366' (PBTD @ 5370'). LD tag jts. TOOH w/tubing. PU & TIH w/RPT & set @ 931'. Load hole & PT casing to 500#/30 min. OK.			
Changed out tbg spools & PT to 800#/15 min. OK. TIH & released RBP. TOOH & LD RBP. TIH w/2-3/8" 4.7# tbg and set @ 5333'			
(new setting depth), w/FN @ 5332'. PT tbg – OK. ND BOP, NU WH. RD & released rig 10/12/07.			
	4		
71 10 10 11 10 11			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE SIGNATURE Populatory Specialist DATE 10/20/07			
SIGNATURE TITLE Regulatory Specialist DATE 10/29/07			
Type or print name Patsy Clugston E-mail address: clugspl@conocophillips.com Telephone No. 505-326-9518			
(This space for State use)			
Deputy Oil 9 9			
APPPROVED BY Conditions of approval, if any:  Deputy Oil & Gas Inspector, DATE District #3			
Conditions of approval, if any:		ווופוע	U(#3