Form 3160-5 (November 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## **SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM A	PPRO	VED
OMB No.	1004	-013:
Expires In	lv 31.	1996

Contract 360

6.	If Indian.	Allottee	or Tribe Name

Jicarilla Tribe

SUBMIT IN TRIPL	ICATE – Other instruc	tions on reverse		If Unit or CA/Agreem	ent, Name and/or N CVD MAR 24 '08	
1. Type of Well				s <sup></sup>	TE STENDED FARE	
X Oil Well Gas Well	Other		8	Well Name and No.	<u>IL CONS, DI</u> V.	
2. Name of Operator	Попи	WAR 1 8 2008		nanza #3	DIST. 3	
Elm Ridge Exploration Comp	nany IIC		10	API Well No.		
3a. Address		3b. Phone No. (includ	mant	-043-20497		
PO Box 156 Bloomfield, NM		505-632-3476 x 2	ington the a Cine			
4. Location of Well (Footage, Sec.,				Lindrtih Gallup [	•	
790' FNL & 790' FWL		,	<u> </u>	County or Parish, State		
Sec. 1-T22N-R3W				indoval, New Mex		
12. CHECK APPROPRIATE BOX	K(ES) TO INDICATE NATU	IRE OF NOTICE, RE	PORT, OR OTHER	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION		- <del> </del>		· · · · · · · · · · · · · · · · · · ·	
Notice of Intent  X Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Star Reclamation Recomplete	البيا	er Shut-Off Integrity	
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon Plug Back	Temporarily Ab Water Disposal	ily Abandon		
Testing has been completed. Final Abdelemnined that the site is ready for final inspection. LLC comparand pump 17 sks of Neet cement is retainer for a plug set at 6190' - 67 5-08, Mix and pump 17 sks of cement and pump 42 sks of cement w/ 2% sks of Neet cement at 2716' - 2272 and pump 51 sks of Neet cement, line at 983'. Plug # 7) 3-6-08, Perfewell w/ cement. Pressure tested we	ny has plugged and abandor spot to end of the TBG, then set to end of the TBG, then set to end with 2% CC at 4232' to 40 CC at 3520' to 3257' wait on 2' tag top of plug at 2186'. Plugump 43 sks below retainer at 4 holes @ 240' TIH to 290' m	ned the above well Fe sting into retainer set a d pump 17 sks of Nee 26' wait on cement ar cement and tag the to a # 6) 3-6-08, Perf 4 I and 8 sks above from ix and pump 98 sks o	oruary 29, 2008 to fat 6810' pump 12 stoement, balance put tag the top of plug professor at 1138' TIH value 1138' to 983', wait of Neet cement to fill	March 6, 2008: Plug ks below retainer and blug from 5778' to 55 g # 3 at 4100'. Plug # 5) 3-5-08, Mi. by/ cement retainer at ton cement and tag to	#1)3-4-08, Mix d 5 sks above 62'. Plug #3) 3- #4) 3-5-08, Mix x and pump 42 set at 1088' mix op of plug w/ wire	
14. I hereby certify that the foregoing Name (Printed/Typed) Sharla	is true and correct O'kelly	Title	Production	Assistant		
Signature (Mole	Otels	March 1	0, 2008			
	THIS SPACE FO	OR FEDERAL OR ST	ATE USE	AN PROPERTY OF THE		
Approved by		Title		Date		
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduct	table title to those rights in the subje					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the united states day talks. Elections of fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD 5

REMOTOR PRED OFFICE

## **CEMENT JOB SUMMARY SHEET**

Job Type			PTA			
Casing Conductor Surface	Size	Weight	Thread 8rd 8rd	Grade	Depth	
Intermediate			<i>8rd</i> 8rd			
Production	5 1/2"	15.5#	8rd			
Drill Pipe/Tbg		4.7#	EUE			
Open Hole	7 7/8"	N/A	N/A	N/A		
			IT INFORMA			
Spacer Bbls		· · · · · · · · · · · · · · · · · · ·	Spacer Type			
Cement 1 Additives	<b>STD</b> 2% C.C. ON T	HE SIDE			263	Sacks
	Weight (lb/gal)	15.60	Yield (cuft/sk	1.18	Water (gal/sk)	5.20
Cement 2 Additives						Sacks
	Weight (lb/gal)		Yield (cuft/sk	)	Water (gal/sk)	
Cement 3 Additives						Sacks
	Weight (lb/gal)		Yield (cuft/sk	)	Water (gal/sk)	
Cement 4 Additives						Sacks
	Weight (lb/gal)		Yield (cuft/sk	)	Water (gal/sk)	
Displacement	H20		8.33	(lb/gal)		
	C	EMENTI	NG EQUIPMI	ENT		
Provider	SUPERIOR W	ELLS SERV	/ICE			
Guide Shoe		ea.	Centralizers		ea.	
Float Shoe		ea.	Turbos		ea.	
Float Collar		ea.	Stop Ring		ea.	
Insert Float		ea.	Threadlock		ea.	

TICKET NUMBER TICKET DATE **JOB LOG** 826 March 6, 2008 ROCKIES COMPANY BDA /STATE COUNTY USA NM Rio Arriba SUPERVISOR CUSTOMER REP/PHONE # ELMRIDGE RESOURCES

JOB TYPE
PTA JERRY BARTH

CONTRACTOR

PPP #2 Sheldon Jones LEASE/WELL# SECTION / TOWNSHIP / RANGE


	Bonanza #3				SECTION / TOWNSHIP / KANGE
Date				Pmps TUBING CASING	Job Description / Remarks
3/3/08	9:30				ARRIVED ON LOCATION
					WENT TO SPOT TRUCKS AND THE PUMP TRUCK GOT STUCK
					CHAINED UP BODY LOAD BULK TRUCK TO PULL OUT PUMP
	10:00				TRUCK AND BROKE A U JOINT
	15:00				CANNOT FIX DRIVELINE CALLED IT A DAY
3/4/08	6:30				ARRIVED ON LOCATION
					SPOT EQUIPMENT
	9:26				START JOB
		2	15.5		LOAD AND TEST TUBING TO 1000PSI
		0.5	5		ESTABLISH INJECTION RATE
		3	98		PULL OUT OF RETAINER AND ROLL HOLE
					PLUG #1
	10:39	2	4		PUMP CEMENT @15.6# 20 SKS TYPE V NEAT
		2	20		SPOT CEMENT TO END OF TUBING
					STING INTO RETAINER
		0.5	25.3		PUMP CEMENT TO 6538'
					PULL OUT OF RETAINER
		0.5	0.5		PUMP .5BBLS TO BALANCE PLUG
					CHECK PLUG BALANCE (PLUG GOOD)
					PULL STINGER OUT OF HOLE
					RUN TUBING AND SET @5776'
					START JOB PLUG #2
		0.5	5		LOAD HOLE AND TEST CASING TO 500PSI (DID NOT TEST)
	15:05	2	3.5		PUMP CEMENT @15.6# 16SKS TYPE V NEAT
		3	21.4		PUMP DISPLACEMENT
	15:17				CHECK PLUG BALANCE (PLUG GOOD)
					PULL 5 STANDS AND REVERSE CIRCULATE WELL
3/5/08	7:30				ARRIVED ON LOCATION
					TAGGED CEMENT @5678'
					LAY DOWN TUBING AND SET @4229
	8:45				START JOB PLUG #3
					LOAD AND TEST CASING TO 500PSI (DID NOT TEST)
	9:12	3	3.5		PUMP CEMENT @15.6# 16SKS TYPE V W/ 3% C.C.
		3	15 5		PUMP DISPLACEMENT
					CHECK PLUG BALANCE (PLUG GOOD)
	9:32	3	21		PULL 5 STANDS AND REVERSE CIRCULATE WELL
					W O C 3 HRS 12:30
					PULL TUBING AND SET @3520' PLUG #4
	13:23	3	4		PUMP CEMENT @15.6# 20SKS TYPEV W/3% C.C.
		3	12.5		PUMP DISPLACEMENT
					CHECK PLUG BALANCE (PLUG GOOD)
		3	14		PULL 5 STANDS AND REVERSE CIRCULATE WELL

		TICKET Number	TICKET DATE	
	IJIM JOB LOG	826	March 5, 2008	
	U AREA	BDA /STATE	COUNTY	
ÚSĀ	ROCKIES		RIO ARRIBA	
SUPERVISOR	COMPANY	cus	TOMER REP/PHONE #	
SHELDON JONES	ELMRIDGE RESOURCES	JERRY BARTH		
API#	JOB TYPE		CONTRACTOR	
	PLUG TO ABANDON			
. LEASE / WELL #	SEC	TION / TOWNSHIP / RANGE		
BONANZA #3				

			Volume	ę Pm	ps :	Job Description // Remarks
Date	TIME	(BPM)	* BBLS	TUBING	CASING	
3/5/08			ļ			W.O.C. 16:00
	ļ					PULL TUBING AND SET @2716
	1001	2.5		<u>-</u>		START JOB PLUG #5
	16:21	2.5	9			PUMP CEMENT @15.6# 42SKS TYPE V NEAT
	16:25	2.5	7.5			PUMP DISPLACEMENT
			10		<del> </del>	CHECK PLUG BALANCE (PLUG GOOD)
	1.5	3	10			PULL 15 STANDS AND REVERSE CIRCULATE WELL
	17:30					END JOB
3/6/08	9:15					ARRIVED ON LOCATION
<del></del>						RIGGING UP PERFORATORS
	9:40					RUN AND SET RETAINER @3300'
	10:18					START JOB PLUG #6
						TEST TUBING TO 2200PSI (TEST GOOD)
			<u> </u>			TEST CASING TO 500PSI (NO TEST)
	10:37					ESTABLISH INJECTION RATE
	10:54	1.3	10.7			PUMP CEMENT @15.6# 51SKS TYPE V NEAT
	11:06	1	25			PUMP DISPLACEMENT
						PULL OUT OF RETAINER
		0.5	0.5			BALANCE PLUG
•						CHECK PLUG BALANCE (PLUG GOOD)
						LAY DOWN 6 JTS
	11:19	2	7			REVERSE CIRCULATE WELL
						START JOB PLUG #7 SURFACE
						SHOT HOLES
	14:10					ESTABLISH INJECTION RATE
	14:22					RUN 9 JTS TO288'
		3	20.5			PUMP CEMENT @15.6# 98SKS TYPE V NEAT
	15:11	0.5	2		-	TOP OFF WELL
	16:00					END JOB
· · · · · · · · · · · · · · · · · · ·						
	1	<del></del>				
·	<u> </u>					
	<del>                                     </del>					
<del>, , , , , , , , , , , , , , , , , , , </del>	<del>  </del>		<u> </u>			
	<del></del>					
· · · · · · · · · · · · · · · · · · ·				· · · ·		
	<del> </del>	····				
	<del>  </del>				<u> </u>	
	1 1					

i

		CII	DEDIODI	WELL SERVICES	INVOICE NUMBER			36- 000826			
	PERIOR L SERVICES	30	PERIOR V	WELL SERVICES		ICE NUMI	BEK	March 6, 2008			
1		WEST	-08a-SALES &	SERVICE FIELD INVOICE		ICE PAGE	1	of of	1		
CHARGE TO	0	WEST.	OUR BY HAND CO	DERCTOR TRANSPORT		ME OR PROJECT		<u>'</u>	10,1	•	
Elmr	idge Resou	irces			Bona	anza #3					
ADDRESS					STATE		COUNTY				
					NM		Rio Arriba				
ADDRESS					FIELD			WELL PERMIT NUMBE	:R	0	
OWNER					SERVICE E	NGINEER	<u></u>	<u> </u>			
					Sheldo	on Jones					
AFE / PURC	HASE ORDER / CONTRACT	T / REFERENCE		IOB TYPE		ON LO	CATION	I	MPLETE		
	-		ĺ	PTA		TIME	9:30 3/3/2008	l .		16:30 3/6/2008	
SIGNATURE				VAME (PLEASE PRINT)			ood and agreed to the	terms and conditions print. LIMITED WARRANTY,		e reverse side	
X			ļ.	Jerry Barth				ower and authority to exe			
LOC	ITEM	QTY	<u> </u>	DESCRIPTION		<u> </u>	DISC ACCT	UNIT PRICE	Α	MOUNT	
36	20-200-0001	300	Milosgo DOT	Units - Cmt - per unit, per m	ono.			7.30		2,190.00	
	20-200-0001	***************************************	<del></del>			way	<del>-</del>				
36	20-200-0002		<del></del>	DOT Units -Cmt - per unit, p			-	4.10		1,230.00	
36			<del></del>	Delivery - per sack, per one	way mile	······································		0.16		4,208.00	
36	20-215-0001		<del></del>	g Service - per sack			-	2.90		762.70	
36	20-225-0020		<del></del>	mped 1,001 to 2,000 psi - firs		Der unit	<del>-</del>	2,340.00		2,340.00	
36	20-220-1000		<del></del>	Irs - Stand-by - per unit, per I	nour		-	492.00		2,952.00	
36	20-299-0005		<del></del>	- Cmt - each, per job			-	784.00		784.00	
	20-299-0006	-	<del></del>	er Left on Well - each, per jo			-	118.00		-	
36	20-299-0008	***************************************	<del></del>	cording System- each, per jo			-	1,180.00		1,180.00	
36	20-299-0010		·····	Mix System (HEMS) - each,	per job		-	714.00		714.00	
36	25-305-1500		<del></del>	pe V - per sack	******************************	7 <del></del>	-	34.20	***********	8,994.60	
36	20-225-1030		<del></del>	ımping 2,001 to 3,000 psi - p	er unit, p	er hour		550.00	************	3,300.00	
36	25-300-0002		<del>}</del>	oride (CaCl2) - per pound			-	0.91		72.80	
36	25-315-0020	5	No Foam 2 -	per gallon			-	135.00		675.00	
-		_	<u> </u>	t			-	~	••••••		
-	<u></u>	_	<u> </u>				-			-	
-	<u></u>	-	<u> </u>	·			-	<u> </u>		_	
-					***************************************	***************************************	-	-			
-		-	<u> </u>	······································			**	-		_	
-		_	<u> </u>	······································			-	<del>-</del>		-	
-		_			·····		~	_		-	
_		-					-	_		-	
-		_					-			-	
_		-					-	-		_	
						Contin	uation Page	\$			
	OR AGENT SIGNATURE !	COMMENTS					Subtotal	\$		29,403.10	
X					l s	pecial Discount Line	ttem Discounts			(14,113.49)	
					sp	ecial Allowance	<b>\$</b> -	\$		_	
	The customer or cust equipment, materials			Terms: Net 30 days. Finance charge 1-1/29 per month on past due accounts. Applicable		Surcharges	Subtotal 3.00%	\$		15,289.61 458.69	
		s field ticket.		taxes will be added on invoice.	, uci	AMOUNT		\$		15,748.30	




{3}PLUG TO ABANDON - Relative Time Chart [36-000826-02-3-RT-1]

Thursday, March 06, 2008

26 of 28

Superior Well Services





{3}PLUG TO ABANDON - Relative Time Chart [36-000826-02-3-RT-2]



\*

**Post Job Summary** 

