					/	
Form 3160-5 (August 1999) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0135 pires: November 30, 2000	
Do not	NDRY NOTICES AND REP	to drill or to re-enter	anle 18 14	14-20-60		
abandoned well. Use form 3160-3 (APD) for such proposals.				NAVAJO	ALLOTTEE	
WIER-4 PH SUBMIT	IN TRIPLICATE - Other instr	uctions on reverse	MAR 2002	7. If Unit or C	CA/Agreement, Name and/or No.	
7() 1 Type of Well ☐ Other ☐					8. Well Name and No. NAVAJO ALLOTTEE GC 1A	
2. Name of Operator BP AMERICA PRODU	CONTRACT:	V	~··&	9. API Well N 30-045-0		
3a. Address P.O. BOX 3092 HOUSTON, TX 77253 3b. Phone No (include area code) Company of the control of the con					10. Field and Pool, or Exploratory BLANCO MESAVERDE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or	Parish, and State	
Sec 25 T28N R9W NWSE 1925FSL 1700FEL				SAN JUA	AN COUNTY, NM	
12. CHECK	X APPROPRIATE BOX(ES)	TO INDICATE NAT	URE OF NOT	ICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSIO	N	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen		Production (Start/Resu	ıme) 🔲 Water Shut-Off	
	☐ Alter Casing	☐ Fracture Tr	eat 🔲	Reclamation	□ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Const	ruction	Recomplete	Other	
☐ Final Abandonment Notice	otice	□ Plug and A	bandon 🔲	Temporarily Abandon	•	
	Convert to Injectio	n Plug Back		'ater Disposal		
If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is rea	anted on 01/29/2002 by Jim Lo	ly, give subsurface locatior de the Bond No. on file wi results in a multiple compl filed only after all requirent wato, BLM, BP Amer	is and measured are the BLM/BIA. Receition or recomplements, including receipt and the control of the control o	nd true vertical depths of a quired subsequent reports tion in a new interval, a F aclamation, have been con	all pertinent markers and zones, shall be filed within 30 days form 3160-4 shall be filed once	
performing a bradenhe location and well servic need to be performed: TIH & set CIBP @ 2350	ad repair on the subject well pring operations were in progres 0'. Run Bond log in 5 1/2" CSC Depending on CMT top SQ2	er following procedure ss when it was appare G to determine CMT to	e (service rig w nt that bradenl op. PU above	as on well head repair CMT top & run		
14. I hereby certify that the fore	Electronic Submission	n #10220 verified by the PRODUCTION COMPA	BLM Well Info	rmation System Farmington		
Name(Printed/Typed) MA	RY CORLEY	Title	AUTHORIZE	ED REPRESENTATI	VE	
Signature (Ele	ectronic Submission May by	lu Date	01/30/2002		ACCEPTED FOR DEGA	
	THIS SPACE	FEDERAL OR	STATE OFF	ICE USE	ruueried fun neco l	
		T_			MAR 1 1 2002	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Approved By

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.



FARMINGTON FIELD OFFICE

Title

Office